



CITROËN



report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO E-HDI EDITION EGS GRAND PICASSO
Colour	Blue
Year of manufacture	2012
Top speed	113 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-11-15
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	9
Total items failed	15

<b>MOT #12</b>	2023-11-16 16:31
MOT test number	540237553428
Result	✓ Passed
Next expiry date	2024-11-15
<b>Advice</b>	Offside Front Play in steering rack inner joint(s)

<b>MOT #11</b>	2023-11-15 10:35
MOT test number	597220742129
Result	✗ Failed
<b>Fail</b>	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
<b>Fail</b>	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
<b>Fail</b>	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Offside Front Inner Track rod end ball joint has excessive play tie rod end (2.1.3 (b) (i))
<b>Fail</b>	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))



<b>MOT #10</b>	2022-09-30 14:14
<b>MOT test number</b>	961496642252
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge wearing edges (5.2.3 (e))

<b>MOT #9</b>	2022-09-30 12:47
<b>MOT test number</b>	610687645988
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge wearing edges (5.2.3 (e))
<b>Fail</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))

<b>MOT #8</b>	2021-08-20 16:35
<b>MOT test number</b>	115351965154
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2020-01-17 17:35
<b>MOT test number</b>	169478435405
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2020-01-17 11:34
<b>MOT test number</b>	954685124745
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge 1.6 - 2mm (5.2.3 (e))
<b>Fail</b>	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Fail</b>	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



**MOT #5** 2019-02-15 15:34

**MOT test number** 987619785770

**Result** ✓ Passed

**MOT #4** 2018-05-16 12:41

**MOT test number** 339988622464

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2017-05-10 12:42

**MOT test number** 823918499476

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** N/s/r tyre wearing on outer edge

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2016-05-18 14:35

**MOT test number** 954543734134

**Result** ✓ Passed

**MOT #1** 2015-05-27 12:52

**MOT test number** 819847645109

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
15 November 2024

**Tax status** Valid until 1 April

**Days left** 336

**MOT expiry date** 15 November 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	EK12AVN
Plate since	2019-03-29
Current registration	EK12AVN
Plate since	2019-03-29

More info >



**Finance check**

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	13
<b>First mileage registration</b>	2012-07-03
<b>Last registration</b>	2023-11-16
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2012-07-03	8 mi
<b>Registration #2</b>	2015-05-27	4.357 mi
<b>Registration #3</b>	2016-05-18	13.059 mi
<b>Registration #4</b>	2017-05-10	17.654 mi
<b>Registration #5</b>	2018-05-16	22.937 mi
<b>Registration #6</b>	2019-02-15	28.741 mi
<b>Registration #7</b>	2020-01-17	35.340 mi
<b>Registration #8</b>	2020-05-27	41.277 mi
<b>Registration #9</b>	2021-05-27	47.214 mi
<b>Registration #10</b>	2022-05-27	53.151 mi
<b>Registration #11</b>	2023-05-27	59.088 mi
<b>Registration #12</b>	2023-11-16	65.025 mi
<b>Registration #13</b>	2024-03-29	70.962 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1520 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBEG0014724