





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 CRDI STYLE BLUE DRIVE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-01-22

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	6

MOT #8	2023-11-03 14:58
MOT test number	951712424173
Result	✓ Passed
Next expiry date	2024-11-15
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2023-11-03 14:58
MOT test number	924707464061
Result	X Failed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))	

MOT #6	2022-11-07 12:28
MOT test number	600155738863
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2021-11-02 13:12
MOT test number	509743635309
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #4 2020-11-04 16:20

MOT test number 808208127288

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-05-10 15:38

MOT test number 148779522715

Result ✓ Passed

MOT #2 2018-05-12 10:52

MOT test number 250417771125

MOT #1 2018-05-12 08:42

MOT test number 952222103695

Result ★ Failed

Pass with rectification Central Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Nail in tyre

Fail Tyre pressure monitoring system inoperative (4.1.D.4)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	UK AIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-16
Last registration	2023-11-03
Complete history	See info



Registration #1	2015-05-16	23 mi
Registration #2	2018-05-12	22.563 mi
Registration #3	2018-05-12	22.564 mi
Registration #4	2019-05-10	28.002 mi
Registration #5	2020-11-04	34.638 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		m

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles 2

Engine number D4FBEZ604522