



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SE
Colour	Silver
Year of manufacture	2005
Top speed	116 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-30
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-16
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	22
Total items failed	16

MOT #21	2023-05-17 14:09
MOT test number	958771131626
Result	✓ Passed
Next expiry date	2024-05-16

MOT #20	2022-07-12 07:49
MOT test number	637094168569
Result	✓ Passed

- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm + bald inner shoulder (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm + perished (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Reverse lamp not working
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm + perished + 2x nails (5.2.3 (e))

**MOT #19**

2022-07-11 10:19

**MOT test number**

949905971580

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm + perished + 2x nails (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Reverse lamp not working
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm + bald inner shoulder (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm + perished (5.2.3 (e))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Tyre has ply or cords exposed worn through to cords on inner shoulder (5.2.3 (d) (ii))

**MOT #18**

2021-08-03 10:32

**MOT test number**

199294083520

**Result**

✓ Passed

**MOT #17**

2020-07-10 15:13

**MOT test number**

968680761874

**Result**

✓ Passed

**MOT #16** 2019-07-20 09:39**MOT test number** 298614261377**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #15** 2018-08-04 09:52**MOT test number** 762548475329**Result** ✓ Passed**MOT #14** 2018-08-04 09:52**MOT test number** 602970115104**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Reversing lamp inoperative (4.6.1 (a))**MOT #13** 2017-08-03 15:22**MOT test number** 570785059497**Result** ✓ Passed**Advice** Vehicle lights flickering.**MOT #12** 2016-08-15 07:52**MOT test number** 513082216813**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #11** 2015-08-17 15:21**MOT test number** 932745858207**Result** ✓ Passed**MOT #10** 2014-06-09 12:04**MOT test number** 437800064170**Result** ✓ Passed**MOT #9** 2014-06-09 12:04**MOT test number** 647600464100**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #8** 2013-06-12 14:07**MOT test number** 947193463192**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.2b)**MOT #7** 2012-06-15 15:29**MOT test number** 479637262136**Result** ✓ Passed**MOT #6** 2011-06-08 15:45**MOT test number** 178489151178**Result** ✓ Passed

**MOT #5** 2011-06-08 09:49**MOT test number** 225429151409**Result** ✗ Failed

- Fail** Centre Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Front brake application uneven (3.7.B.2)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2010-05-27 10:04**MOT test number** 201257540121**Result** ✓ Passed**MOT #3** 2009-06-12 17:14**MOT test number** 741953469192**Result** ✓ Passed**MOT #2** 2009-06-12 08:58**MOT test number** 304633969193**Result** ✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Stop lamp not working (1.2.1b)

**MOT #1** 2008-12-11 10:09**MOT test number** 573216148371**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
16 May 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	16 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>EJ55WCV</b>
Plate since	2024-03-28
Current registration	<b>EJ55WCV</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-14
Last registration	2023-05-17
Complete history	<a href="#">See info</a>



Registration #1	2005-12-14	8 mi
Registration #2	2008-12-11	21.948 mi
Registration #3	2009-06-12	22.890 mi
Registration #4	2009-06-12	22.890 mi
Registration #5	2010-05-27	26.045 mi
Registration #6	2011-06-08	29.292 mi
Registration #7	2011-06-08	29.295 mi
Registration #8	2012-06-15	32.420 mi
Registration #9	2013-06-12	35.545 mi
Registration #10	2014-06-09	38.742 mi
Registration #11	2015-08-17	41.046 mi
Registration #12	2016-08-22	45.277 mi
Registration #13	2017-08-22	49.508 mi
Registration #14	2018-08-22	53.739 mi
Registration #15	2019-08-22	57.970 mi
Registration #16	2020-08-22	62.201 mi
Registration #17	2021-08-22	66.432 mi
Registration #18	2022-08-22	70.663 mi
Registration #19	2023-05-17	74.894 mi
Registration #20	2023-05-17	79.125 mi
Registration #21	2023-05-17	83.356 mi
Registration #22	2023-05-17	87.587 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX7G2610565