





General information

Make	FIAT
Model 500X MULTIAIR LOUNGE DDCT	
Colour	Black
Year of manufacture	2017
Top speed	118 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E







Internet history

Entry 2	
Date	2021-08-13
Pictures	42
Listing price	View report



source: heycar.co.uk

Entry 1


Pictures

Listing price

2021-08-09 12

View report

source: cargurus.co.uk









MOT history

MOT expiry date	2024-08-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #6	2023-08-16 11:28	
MOT test number	663183637106	
Result	✓ Passed	
Next expiry date	2024-08-22	
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		

МОТ #5	2022-08-17 14:02	
MOT test number	250925538193	
Result	✓ Passed	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened	both rear (1.1.14 (a) (ii))	



KM66KKG report date: 2024-03-28

MOT #4	2022-08-17 13:51	
MOT test number	909859172598	
Result	🗙 Failed	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i))	the ply or cords	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but ingress of dirt (2.1.3 (g) (i))	t preventing the	
Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both	rear (1.1.14 (a) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but p ingress of dirt (2.1.3 (g) (i))	preventing the	

MOT #3	2021-08-23 12:28
MOT test number	702601753759
Result	✓ Passed

MOT #2		2021-01-26 12:45
MOT test	number	313441721215
Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1	2020-01-06 11:01
MOT test number	134007546680
Result	✓ Passed



KM66KKG report date: 2024-03-28

Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 22 August 2024	✓ MOT
Tax status			Valid until 1 August
Days left			93
MOT expiry date			22 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
See in this check if this that had uncreated under plates.	
	,
	8000-20-20





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



KM66KKG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-30
Last registration	2023-08-16
Complete history	See info



Registration #1	2017-01-30	6 mi
Registration #2	2020-01-06	28.833 mi
Registration #3	2021-01-26	39.981 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >



KM66KKG report date: 2024-03-28

Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1796 mm
Height	1600 mm
Length	4248 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	2199521