





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S ALL4
Colour	Green
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-09-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-24
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	6

MOT #12		2023-09-25 08:50
MOT test i	number	764295863558
Result		✓ Passed
Next expir	y date	2024-09-24
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Driving stabilization restricted warning	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #11		2022-09-06 09:43
MOT test	number	525021629402
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #10	2021-09-17 09:19
MOT test number	500902035820
Result	✓ Passed
Advice Undertrays fitted obscuring inspection of some components	

CarCheck.co.uk page 3/12



MOT #9 2021-09-16 11:58

MOT test number 870755531584

Result X Failed

Fail Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Advice Undertrays fitted obscuring inspection of some components

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2021-03-27 11:34

MOT test number 741175560358

Advice Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #7 2021-03-26 11:14

MOT test number 347352195454

Result × Failed

Advice Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-03-23 11:27

MOT test number 878885806996

MOT #5 2019-03-14 09:45

MOT test number 171755460749

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/12



MOT #4

MOT test number

659149555896

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Offside Headlamp not working on main beam (1.7.5a)

MOT #2	2017-03-02 10:29
MOT test number	642298575385
Result	✓ Passed
MOT #1	2016-03-15 15:17
MOT test number	270384386070
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manus .	

	More info >
	,
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-27
Last registration	2023-09-25
Complete history	See info



Registration #1	2013-03-27	29 mi
Registration #2	2016-03-15	16.338 mi
Registration #3	2017-03-02	24.050 mi
Registration #4	2018-03-07	33.028 mi
Registration #5	2018-03-08	33.028 mi
Registration #6	2019-03-14	42.658 mi
Registration #7	2020-03-23	50.377 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 44
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.372 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

B221J286