



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	2003
Top speed	146 mph
0 - 60 mph	8.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	3.222 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-08
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-22
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	28
Total items failed	14

MOT #21	2023-11-23 17:50
MOT test number	681903391381
Result	✓ Passed
Next expiry date	2024-11-22

MOT #20	2023-11-16 15:45
MOT test number	632433519046
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))
Fail	Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Front Registration plate does not conform to the specified requirements (0.1 (d))
Fail	Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
Fail	Rear Registration plate does not conform to the specified requirements (0.1 (d))

**MOT #19** 2021-09-13 14:36**MOT test number** 373472888697**Result** ✓ Passed**MOT #18** 2020-09-19 14:53**MOT test number** 355378955901**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #17** 2019-09-07 10:07**MOT test number** 587882502504**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Advice** Offside Rear tail lamp slightly damage**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2018-08-25 12:29**MOT test number** 471658491034**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15** 2017-09-09 10:57**MOT test number** 471049079160**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**MOT #14** 2016-09-14 16:14**MOT test number** 323586381898**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #13** 2015-06-16 10:57**MOT test number** 546367265116**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #12**

2014-06-17 12:31

MOT test number

138548964169

Result

✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #11**

2013-05-31 07:38

MOT test number

968451053108

Result

✓ Passed

MOT #10

2012-06-20 09:12

MOT test number

277902172191

Result

✓ Passed

MOT #9

2012-06-19 10:28

MOT test number

116511372177

Result

✗ Failed

Notice Nearside front tyre outer edge worn**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Offside rear tyre worn on outer edge**Fail** Offside Front Direction indicator not working (1.4.A.2c)**Notice** Offside front tyre worn on outer and inner edge

**MOT #8** 2011-06-20 10:45**MOT test number** 195411771154**Result** ✓ Passed**MOT #7** 2011-06-17 09:40**MOT test number** 597668961164**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Upper Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear Upper Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #6** 2010-05-03 14:59**MOT test number** 521443420148**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-03-14 10:46**MOT test number** 990253879024**Result** ✓ Passed**MOT #4** 2008-03-15 10:02**MOT test number** 102495878431**Result** ✓ Passed**MOT #3** 2008-03-15 10:02**MOT test number** 620395178081**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)



MOT #2	2007-03-17 09:29
MOT test number	683596877056
Result	✓ Passed

MOT #1	2006-03-20 11:48
MOT test number	522469776075
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
22 November 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 LR520MA
Plate since	2019-06-29
Current registration	 LR520MA
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-01-10
Last registration	2023-11-23
Complete history	See info



Registration #1	2003-01-10	28 mi
Registration #2	2006-03-20	60.103 mi
Registration #3	2007-03-17	74.576 mi
Registration #4	2008-03-15	90.617 mi
Registration #5	2009-03-14	101.843 mi
Registration #6	2010-05-03	116.496 mi
Registration #7	2011-06-17	129.971 mi
Registration #8	2011-06-20	129.971 mi
Registration #9	2012-06-19	143.166 mi
Registration #10	2012-06-20	143.166 mi
Registration #11	2013-05-31	150.667 mi
Registration #12	2013-05-31	150.667 mi
Registration #13	2013-05-31	150.667 mi
Registration #14	2013-05-31	150.667 mi
Registration #15	2013-05-31	150.667 mi
Registration #16	2013-05-31	150.667 mi
Registration #17	2013-05-31	150.667 mi
Registration #18	2013-05-31	150.667 mi
Registration #19	2013-05-31	150.667 mi
Registration #20	2013-05-31	150.667 mi
Registration #21	2013-05-31	150.667 mi
Registration #22	2013-05-31	150.667 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1886 mm
Height	1497 mm
Length	5113 mm
Wheel base	2965 mm
Kerb weight	1850 kg

Additional information

Fuel tank capacity	88 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	64896030016902