





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GTD TDI
Colour	Silver
Year of manufacture	2018
Top speed	144 mph
0 - 100 km/h	7.5 seconds
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	135 kW / 184 HP / 181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-10-08


Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Data	2021 00 00
Date	2021-09-08
Date	2021 03 00

Pictures 9

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1


Date 2021-08-10

Pictures 9

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-07
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #4	2023-11-06 11:46
MOT test number	166501350667
Result	✓ Passed
Next expiry date	2024-11-07
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2022-11-08 13:33
MOT test	number	202561564580
Result		✓ Passed
Advice	Sound deadening material not fully secure Bonnet (8.1.1 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	n) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #2 2021-11-08 15:16

MOT test number 263241631040

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Sound deadening material not fully secure under bonnet (8.1.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2021-03-04 11:54

MOT test number 640308575969

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



DK18XOC

report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Damage 2

Type

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



DK18XOC

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-02
Last registration	2023-11-06
Complete history	See info



Registration #1	2018-03-02	26 mi
Registration #2	2021-03-04	39.179 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4268 mm
Wheel base	2626 mm
Kerb weight	1377 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	DGCA206008