





report date: 2024-03-28

### General information

Make	SUZUKI
Model	IGNIS SZ-T DUALJET
Colour	White
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	120 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

	_
Entry	2

Date	2021-02-04
Pictures	0
Listing price	<u>View report</u>

#### source: autoonline.co.uk

#### Entry 1

, _	
Date	2021-02-04
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2024-05-14
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #3	2023-05-15 09:56
MOT test number	391634075143
Result	✓ Passed
Next expiry date	2024-05-14
Advice Offside Rear Tyre slightly damaged/cracking or perishing perished and	cracked (5.2.3 (d) (ii))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3	(e))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting rear bush (5.3.4 (a) (i))	ng in excessive movement
Minor Windscreen damaged but not adversely affecting driver's view small ch (3.2 (a) (i))	ip in passenger swept area
Advice Front Brake pad(s) wearing thin inner pads appear to be worn (1.1.13	(a) (ii))
Advice Rear wiper blade deteriorated	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing perished ar	nd cracked (5.2.3 (d) (ii))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting rear bush (5.3.4 (a) (i))	in excessive movement
Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2		2022-05-10 09:55
MOT test	number	917858871952
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #1	2021-04-28 14:33
MOT test number	564333719050
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	14 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra SUZUKI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	hictory
OWITE	HIISLOLY

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
manners and the same of the sa	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-04-20
Last registration	2023-05-15
Complete history	See info



Registration #1	2018-04-20	11 mi
Registration #2		71.777 es
Registration #3		D.777 66
Registration #4		11.777 es
Registration #5		11.777 no
Designation #6		

Registration #6

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	87%
Children	79%
Pedestrian	77%
Safety systems	60%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1690 mm
Height	1595 mm
Length	3700 mm
Wheel base	2435 mm
Kerb weight	885 kg
Max. allowed weight	1330 kg

# Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K12C-5248274

CarCheck.co.uk page 11/11