



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V SPORT
Colour	Blue
Year of manufacture	-
Top speed	127 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #17	2021-07-14 15:40
MOT test number	980099703614
Result	✓ Passed
Next expiry date	2022-07-13
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Brake hose has slight corrosion to ferrule both front (1.1.12 (f) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
Minor	Windscreen wiper blade defective both front smearing slightly (3.4 (b) (i))

MOT #16	2020-06-10 08:08
MOT test number	552377072024
Result	✓ Passed

MOT #15	2019-06-12 08:22
MOT test number	717644533710
Result	✓ Passed

MOT #14	2018-06-13 08:28
MOT test number	150659702744
Result	✓ Passed

MOT #13	2017-06-14 08:12
MOT test number	795639901368
Result	✓ Passed

MOT #12	2016-06-15 08:22
MOT test number	505104110762
Result	✓ Passed

**MOT #11** 2015-07-03 14:57**MOT test number** 749754785132**Result** ✓ Passed**MOT #10** 2015-07-03 09:22**MOT test number** 746774685170**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #9** 2014-05-12 14:33**MOT test number** 218542634177**Result** ✓ Passed**MOT #8** 2013-08-13 14:29**MOT test number** 385555123454**Result** ✓ Passed**MOT #7** 2013-08-01 11:16**MOT test number** 659273513254**Result** ✗ Failed**Fail** Main beam 'tell-tale' not working (1.7.4c)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #6** 2012-08-29 15:01**MOT test number** 398032842405**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** M.i..l light on**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2011-08-08 10:17**MOT test number** 388130521496**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-08-02 15:47**MOT test number** 669584211217**Result** ✗ Failed**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front coil spring fractured (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-09-14 11:57**MOT test number** 800537550201**Result** ✓ Passed



MOT #2	2009-10-01 11:23
MOT test number	460434279205
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-09-04 14:28
MOT test number	291948548217
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FN55TEJ
Plate since	2019-03-29
Current registration	 FN55TEJ
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-09-21
Last registration	2021-07-14
Complete history	See info



Registration #1	2005-09-21	25 mi
Registration #2	2008-09-04	17.796 mi
Registration #3	2009-10-01	22.359 mi
Registration #4	2010-09-14	27.705 mi
Registration #5	2011-08-02	34.847 mi
Registration #6	2011-08-08	34.847 mi
Registration #7	2012-08-29	48.150 mi
Registration #8	2013-08-13	60.694 mi
Registration #9	2014-05-12	67.017 mi
Registration #10	2015-05-20	75.377 mi
Registration #11	2016-05-20	75.377 mi
Registration #12	2017-05-20	75.377 mi
Registration #13	2018-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi
Registration #16	2021-05-20	75.377 mi
Registration #17	2022-05-20	75.377 mi
Registration #18	2023-05-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1685 mm
Height	1349 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1190 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	20FP2431