



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	2003
Top speed	114 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption




Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-05-20
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-03-31
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	44
Total items failed	22

MOT #24	2021-03-12 15:53
MOT test number	296671448977
Result	✓ Passed
Next expiry date	2022-03-31

MOT #23	2021-03-12 11:12
MOT test number	552893706065
Result	✗ Failed
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))	
MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2020-03-19 12:40
MOT test number	607416133232
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Play in steering rack inner joint(s)

**MOT #21**

2020-03-19 09:53

MOT test number

957883468886

Result**✗ Failed****Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Pass with rectification** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Play in steering rack inner joint(s)**MOT #20**

2019-03-25 11:53

MOT test number

908453842661

Result**✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Oil leak, but not excessive ENGINE (8.4.1 (a) (i))

**MOT #19**

2019-03-22 12:33

MOT test number

188184934101

Result**✗ Failed**

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Play in steering rack inner joint(s)

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Oil leak, but not excessive ENGINE (8.4.1 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Play in steering rack inner joint(s)

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))

MOT #18

2018-03-29 13:57

MOT test number

985892664665

Result**✓ Passed**

Advice Front Oil leak engine oil leaks

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt clip deteriorated and leaking (2.5.C.1a)

**MOT #17** 2017-03-13 11:44**MOT test number** 547265581814**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Oil leak engine**Advice** Offside Front Play in steering rack inner joint(s)**MOT #16** 2016-04-01 10:52**MOT test number** 530386740673**Result** ✓ Passed**MOT #15** 2015-03-11 12:30**MOT test number** 759310675021**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #14** 2015-03-11 12:30**MOT test number** 759520675086**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #13** 2014-03-19 13:17**MOT test number** 887138374049**Result** ✓ Passed

**MOT #12** 2014-03-19 13:17**MOT test number** 806028074056**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #11** 2014-03-07 12:07**MOT test number** 765896964093**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** O/S/F Tyre has large radial cracks in tread also nail in tread.**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10**

2014-02-27 13:56

MOT test number

557448654048

Result

✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Nearside Side repeater incorrect colour (1.4.A.2f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Battery insecure (1.9.1)
- Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Side repeater incorrect colour (1.4.A.2f)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #9

2013-02-19 10:07

MOT test number

199700453024

Result

✓ Passed

MOT #8

2012-02-13 15:06

MOT test number

698974542091

Result

✓ Passed

- Advice** Offside rear brake grabbing slightly (3.7.A.5b)
- Notice** Front Brake Pads worn close to minimum thickness of 1.5mm.(Only outers can be visually assessed)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2011-02-14 12:24
MOT test number	989725341084
Result	✓ Passed
MOT #6	2009-09-08 16:48
MOT test number	940451959213
Result	✓ Passed
MOT #5	2009-09-08 14:10
MOT test number	924891759220
Result	✗ Failed
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
MOT #4	2008-09-09 14:51
MOT test number	710503158220
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
MOT #3	2008-09-09 14:51
MOT test number	101823758238
Result	✓ Passed
MOT #2	2007-09-04 14:37
MOT test number	290197547271
Result	✓ Passed
MOT #1	2006-09-13 16:02
MOT test number	610816256296
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 UK XXXXXX
Plate since	2024-03-28
Current registration	 UK XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-29
Last registration	2021-03-12
Complete history	See info



Registration #1	2003-09-29	20 mi
Registration #2	2006-09-13	17.986 mi
Registration #3	2007-09-04	23.547 mi
Registration #4	2008-09-09	28.071 mi
Registration #5	2009-09-08	29.820 mi
Registration #6	2009-09-08	29.820 mi
Registration #7	2011-02-14	38.908 mi
Registration #8	2012-02-13	48.484 mi
Registration #9	2013-02-19	58.016 mi
Registration #10	2014-02-27	67.934 mi
Registration #11	2014-03-07	68.058 mi
Registration #12	2014-03-19	68.495 mi
Registration #13	2015-03-20	78.577 mi
Registration #14	2015-03-20	78.577 mi
Registration #15	2015-03-20	78.577 mi
Registration #16	2015-03-20	78.577 mi
Registration #17	2015-03-20	78.577 mi
Registration #18	2015-03-20	78.577 mi
Registration #19	2015-03-20	78.577 mi
Registration #20	2015-03-20	78.577 mi
Registration #21	2015-03-20	78.577 mi
Registration #22	2015-03-20	78.577 mi
Registration #23	2015-03-20	78.577 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Max. allowed weight	1729 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	FX3W1998227