





report date: 2024-03-28

General information

Make	BMW
Model	116 116D SE
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	116 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.496 сс
Cylinders	3
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	96 g/km
CO2 label	А



CarCheck.co.uk page 1/11



FL67ARZ

report date: 2024-03-28


Internet history

Entry 2

Date 2021-09-17


Pictures 60

Listing price View report









source: autotrader.co.uk

Entry 1

Date	2021-08-19
Pictures	6

6

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #5	2023-08-18 07:51
MOT test number	621487598277
Result	✓ Passed
Next expiry date	2024-08-24

MOT #4	2022-08-08 09:41
MOT test number	624082960430
Result	✓ Passed

MOT #3	2021-08-25 14:08
MOT test number	315515598187
Result	✓ Passed

MOT #2	2020-10-02 16:06
MOT test number	695109234108
Result	./ Passed

Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 3/11



MOT #1 2020-10-02 14:08

MOT test number 455610190603

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge completely smooth (5.2.3 (e))

Fail Offside Front Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK L
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-10-05
Last registration	2023-08-18
Complete history	See info



Registration #1	2017-10-05	7 mi
Registration #2	2020-10-02	51.067 mi
Registration #3	2020-10-02	51.067 mi
Registration #4		11.777 es
Registration #5		91.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11




Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1984 mm
Height	1413 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1350 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11