





General information

| Make | MINI |
|---------------------|----------------|
| Model | MINI COOPER D |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 122 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 112 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | А |





Internet history

| Entry 4 | |
|---------------|--------------------|
| Date | 2021-08-12 |
| Pictures | 11 |
| Listing price | <u>View report</u> |




source: autotrader.co.uk

| Entry 3 | |
|---------------|-------------|
| Date | 2021-07-22 |
| Pictures | 11 |
| Listing price | View report |
| | |



source: autotrader.co.uk

| Entry 2 | |
|---------------|-------------|
| Date | 2021-06-30 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk

Entry 1 Date CarCheck.co.uk

2021-06-10

Pictures

Listing price

11

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-01 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 2 |

| MOT #11 | 2023-08-02 11:01 |
|------------------|------------------|
| MOT test number | 941303484851 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-01 |

| MOT #10 | 2022-07-11 16:13 |
|-----------------|------------------|
| MOT test number | 514489528145 |
| Result | ✓ Passed |

| MOT #9 | | 2020-12-15 13:04 |
|----------|---|------------------|
| MOT test | number | 175678310934 |
| Result | | ✓ Passed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #8 | 2019-05-20 10:56 |
|-----------------|------------------|
| MOT test number | 464698100150 |
| Result | ✓ Passed |





| MOT #7 | 2018-05-14 15:46 |
|-------------------------|--|
| MOT test number | 599510547939 |
| Result | ✓ Passed |
| | worn, pitted or scored, but not seriously weakened (3.5.1i) |
| MOT #6 | 2017-05-09 14:41 |
| MOT test number | 571316934421 |
| Result | ✓ Passed |
| МОТ #5 | 2016-04-12 10:34 |
| MOT test number | 550454217694 |
| Result | ✓ Passed |
| МОТ #4 | 2015-03-20 11:31 |
| MOT test number | 568409775090 |
| Result | ✓ Passed |
| МОТ #3 | 2015-03-20 11:31 |
| MOT test number | 115889375027 |
| Result | × Failed |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| МОТ #2 | 2014-04-03 15:19 |
| MOT test number | 176263894488 |
| Result | ✓ Passed |
| MOT #1 | 2014-04-03 15:19 |
| MOT test number | 187393994469 |
| Result | × Failed |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) |



Tax & MOT check

| Tax due: 1 August 2024 | ✓ xed | Expires: 1 August 2024 | √ МОТ |
|----------------------------------|----------|----------------------------------|------------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 95 |
| MOT expiry date | | | 1 August 2024 |
| Full MOT history | | | <u>See MOT history</u> |
| Tax calculation | | | |
| Vehicle class | | 49 | |

| Band | A |
|---|----------------|
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******* | |
| ****** | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | 9 |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2011-02-04 |
| Last registration | 2023-08-02 |
| Complete history | See info |



| Registration #1 | 2011-02-04 | 23 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2014-04-03 | 20.410 mi |
| Registration #3 | 2015-03-20 | 20.438 mi |
| Registration #4 | 2016-04-12 | 41.711 mi |
| Registration #5 | 2017-05-09 | 54.868 mi |
| Registration #6 | 2018-05-14 | 65.439 mi |
| Registration #7 | 2019-05-20 | 68.824 mi |
| Registration #8 | | 11.777 mil |
| | | |
| Registration #9 | | 11.777 mi |
| Registration #9 Registration #10 | | 00.000 est |
| - | | 01.000 est 01.000 est 01.000 est |
| Registration #10 | | 00.000 est 0.000 est 00.000 est 00.000 est |
| Registration #10 Registration #11 | | 01.000 est 01.000 est 01.000 est 01.000 est 01.000 est |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1683 mm |
| Height | 1407 mm |
| Length | 3723 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1540 kg |
| Additional information | |
| Fuel tank capacity | 40 I |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 11/11 |

| Number of axles | 2 |
|-----------------|----------|
| Engine number | 70757967 |