




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI DSG (170BHP)
Colour	Blue
Year of manufacture	2006
Top speed	135 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-17
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-04-22
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	8

MOT #17	2022-04-21 14:14
MOT test number	453662110523
Result	✓ Passed
Next expiry date	2023-04-22
Advice	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-04-23 15:30
MOT test number	163601525603
Result	✓ Passed
MOT #15	2020-01-28 13:32
MOT test number	614578810006
Result	✓ Passed

**MOT #14**

2019-01-28 17:54

**MOT test number**

980254158237

**Result**

✓ Passed

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13**

2019-01-25 16:32

**MOT test number**

253183721747

**Result**

✗ Failed

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #12**

2017-12-08 15:58

**MOT test number**

964463091433

**Result**

✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #11**

2017-12-08 10:36

**MOT test number**

494439526310

**Result****✗ Failed****Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** EML Light on.**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10**

2016-11-28 10:07

**MOT test number**

284012878941

**Result****✓ Passed****Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both side front (2.4.G.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Front constant velocity joint gaiter damaged, but preventing the ingress of dirt both side front (2.5.C.1a)

**MOT #9** 2015-12-09 17:57**MOT test number** 140235288816**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-12-09 13:40**MOT test number** 299543500478**Result** ✗ Failed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear coil spring broken (2.4.C.1a)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #7** 2015-04-18 13:57**MOT test number** 188838205166**Result** ✓ Passed**MOT #6** 2013-08-28 11:07**MOT test number** 359250643221**Result** ✓ Passed**MOT #5** 2012-07-05 09:40**MOT test number** 296527382154**Result** ✓ Passed



MOT #4 2011-07-13 14:09

MOT test number 138284591193

Result ✓ Passed

MOT #3 2010-07-21 14:59

MOT test number 644952700298

Result ✓ Passed

MOT #2 2010-04-08 09:41

MOT test number 960118490033

Result ✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2009-04-07 14:13

MOT test number 641827099071

Result ✓ Passed

**Notice** Nail in offside rear tyre



Tax & MOT check

X

Untaxed

Tax expired:  
30 September 2022

X

MOT

Expired:  
22 April 2023

Tax status	Expired at 30 September
Days left	578 days too late
MOT expiry date	22 April 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BK06UYH</b>
Plate since	2024-03-29
Current registration	 <b>BK06UYH</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-04-11
Last registration	2022-04-21
Complete history	<a href="#">See info</a>



Registration #1	2006-04-11	26 mi
Registration #2	2009-04-07	35.123 mi
Registration #3	2010-04-08	46.853 mi
Registration #4	2010-07-21	49.165 mi
Registration #5	2011-07-13	53.516 mi
Registration #6	2012-07-05	63.130 mi
Registration #7	2013-08-28	77.362 mi
Registration #8	2015-04-18	89.374 mi
Registration #9	2015-12-09	97.484 mi
Registration #10	2015-12-09	97.484 mi
Registration #11	2015-12-09	97.484 mi
Registration #12	2015-12-09	97.484 mi
Registration #13	2015-12-09	97.484 mi
Registration #14	2015-12-09	97.484 mi
Registration #15	2015-12-09	97.484 mi
Registration #16	2015-12-09	97.484 mi
Registration #17	2015-12-09	97.484 mi
Registration #18	2015-12-09	97.484 mi
Registration #19	2015-12-09	97.484 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

BMN014736