



General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SHUTTLE SE LWB 104TDI
Colour	Grey
Year of manufacture	2005
Top speed	99 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	208 g/km
CO2 label	K








Internet history

Entry 2

Date	2021-10-07
Pictures	25
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-17
Pictures	59
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-28
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	29
Total items failed	19

MOT #22	2023-08-29 11:39
MOT test number	850013275739
Result	✓ Passed
Next expiry date	2024-08-28

MOT #21	2022-07-07 13:50
MOT test number	206930120818
Result	✓ Passed

MOT #20	2021-02-12 11:36
MOT test number	436822637517
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #19

2020-02-03 12:53

MOT test number

838693569344

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #18**

2020-01-29 11:33

MOT test number

910210862605

Result**✗ Failed**

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Parking brake inoperative on one side nearside rear not working (1.4.1 (a))

Fail Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #17

2019-02-13 15:24

MOT test number

668879642415

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2019-02-13 13:04**MOT test number** 269300690830**Result** ✗ Failed

Fail Offside Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2018-02-12 15:19**MOT test number** 599064386189**Result** ✓ Passed**MOT #14** 2018-02-08 10:28**MOT test number** 171213089747**Result** ✗ Failed

Advice Nearside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)

Fail Registration plate lamp not working (1.1.C.1d)

Fail Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Central Brake cable has wires broken and is significantly weakened (3.5.1b)

MOT #13 2017-02-03 15:48**MOT test number** 981896570120**Result** ✓ Passed

**MOT #12** 2017-02-03 11:35**MOT test number** 691271956172**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #11** 2016-01-14 12:42**MOT test number** 622975659533**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Steering system has slight free play detected at steering wheel (2.2.A.1b)**Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #10** 2015-01-12 14:21**MOT test number** 838592015005**Result** ✓ Passed**MOT #9** 2013-12-17 14:43**MOT test number** 248941653327**Result** ✓ Passed**MOT #8** 2012-12-20 19:05**MOT test number** 276255652321**Result** ✓ Passed

**MOT #7** 2011-12-17 09:42**MOT test number** 955421451374**Result** ✓ Passed**Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Air bag warning light on dash**MOT #6** 2011-12-17 09:42**MOT test number** 848551751361**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Air bag warning light on dash**MOT #5** 2011-01-05 17:37**MOT test number** 625715101079**Result** ✓ Passed**MOT #4** 2011-01-05 17:37**MOT test number** 298775801043**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2010-01-05 12:55**MOT test number** 443725100071**Result** ✓ Passed



MOT #2	2009-02-10 09:58
MOT test number	202741849050
Result	✓ Passed
Advice	Brake pad(s) wearing thin (3.5.1g)

MOT #1	2008-02-08 16:43
MOT test number	750939338061
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	MA05NTU
Plate since	2019-03-28
Current registration	MA05NTU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-21
Last registration	2023-08-29
Complete history	See info



Registration #1	2005-03-21	10 mi
Registration #2	2008-02-08	39.305 mi
Registration #3	2009-02-10	67.796 mi
Registration #4	2010-01-05	87.415 mi
Registration #5	2011-01-05	91.751 mi
Registration #6	2011-12-17	101.272 mi
Registration #7	2012-12-20	106.149 mi
Registration #8	2013-12-17	110.430 mi
Registration #9	2015-01-12	119.522 mi
Registration #10	2016-01-14	130.711 mi
Registration #11	2017-02-03	140.002 mi
Registration #12	2017-02-03	140.002 mi
Registration #13	2018-02-03	150.002 mi
Registration #14	2019-02-03	160.002 mi
Registration #15	2020-02-03	170.002 mi
Registration #16	2021-02-03	180.002 mi
Registration #17	2022-02-03	190.002 mi
Registration #18	2023-02-03	200.002 mi
Registration #19	2024-02-03	210.002 mi
Registration #20	2025-02-03	220.002 mi
Registration #21	2026-02-03	230.002 mi
Registration #22	2027-02-03	240.002 mi
Registration #23	2028-02-03	250.002 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	5290 mm
Kerb weight	2164 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Number of axles	2
Engine number	AXB 092525