





report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI SE TDV
Colour	Grey
Year of manufacture	2008
Top speed	131 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/13



Internet history


Entry 2

Date 2022-01-30

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-08
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	26
Total items failed	0

MOT #14		2024-02-05 16:46
MOT test	number	614200068359
Result		✓ Passed
Next expi	ry date	2025-02-08
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Advice (5.3.4 (a)	Offside Front Upper Suspension arm pin or bush worn but not resulting in (i))	excessive movement
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))

MOT #13	2023-02-09 10:29
MOT test number	562342511087
Result	✓ Passed
Advice Engine cover & under tray fitted	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2023-02-01 17:02

MOT test number 434285368474

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))

DANGEROUS Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure edge all round (5.2.3 (d) (ii))

MAJOR Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

DANGEROUS Offside Front Tyre has ply or cords damaged sidewalls & blistering inner edge (5.2.3 (d) (ii))

MAJOR Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect no pattern check bulb (4.1.2 (c))

Advice Engine cover & under tray fitted

MOT #11 2021-07-19 15:27

MOT test number 404693912271

Result

Passed

Advice Under tray fitted

Advice Brake disc worn, pitted or scored, but not seriously weakened both front and rear (1.1.14 (a) (ii))

Advice Suspension component pin or bush slightly worn (5.3.4 (a) (i))

MOT #10 2020-06-10 16:29

MOT test number 771716471100

Result ✓ Passed

MOT #9 2019-06-20 11:08

MOT test number 769369151108

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8	2018-06-26 14:27
MOT test number	814401245683
Result	✓ Passed
MOT #7	2017-06-08 16:22
MOT test number	866847789247
Result	✓ Passed
MOT #6	2016-05-21 10:51
MOT test number	402804223609
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2015-05-02 14:36
MOT test number	235682325464
Result	✓ Passed
MOT #4	2014-05-13 13:01
MOT test number	236543334142
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3		2013-05-08 14:44
MOT test	number	679358323132
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2012-05-01 11:07
MOT test nur	nber	966202522158
Result		✓ Passed
MOT #1		2011-05-12 12:02
MOT test nur	nber	226202531175
Result		✓ Passed
Advice Of	fside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Ne	earside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when misterly		
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		/e?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-04-30
Last registration	2024-02-05
Complete history	See info



Registration #1	2008-04-30	22 mi
Registration #2	2011-05-12	31.334 mi
Registration #3	2012-05-01	41.026 mi
Registration #4	2013-05-08	49.962 mi
Registration #5	2014-05-13	58.596 mi
Registration #6	2015-05-02	64.837 mi
Registration #7	2016-05-21	67.367 mi
Registration #8	2017-06-08	74.192 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

CAG 017564