





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	Purple
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-12-11

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-23
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #10		2023-11-15 10:41
MOT test	number	194816565380
Result		✓ Passed
Next expir	y date	2024-11-23
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9			2023-11-15 10:41
MOT test i	number		841917442309
Result			× Failed
Pass wit	h rectification	Offside Headlamp aim projected	beam image is obviously incorrect (4.1.2 (c))
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))			
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))			
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))			
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))			

CarCheck.co.uk page 3/12



Result

PK15KZF
report date: 2024-03-28

X Failed

MOT #8 2022-11-22 13:01
MOT test number 613719366862

Result

Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #7 2022-11-22 13:01

MOT test number 387575124211

Pass with rectification Reversing lamp inoperative (4.6.1 (a))

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #6 2021-11-13 11:32

MOT test number 181867038392

Result ✓ Passed

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #5 2020-10-28 16:39

MOT test number 563787430997

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



PK15KZF

report date: 2024-03-28

MOT #4

MOT test number

Result

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Rear Exhaust system insecure (6.1.2 (a))

MOT test number

735580415552

Result

Advice
Offside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))

Advice
Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))

MOT #2

MOT test number

801017407611

Result

✓ Passed

MOT #1

MOT test number

Result

Fail Offside Front Tyre has ply or cords exposed inner wall (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 23 November 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



PK15KZF

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



PK15KZF

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-31
Last registration	2023-11-15
Complete history	See info



Registration #1	2015-03-31	6 mi
Registration #2	2018-05-24	11.726 mi
Registration #3	2018-05-24	11.726 mi
Registration #4	2019-05-21	13.747 mi
Registration #5	2020-10-28	26.530 mi
Registration #6	2020-10-28	26.531 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71,777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120080873

CarCheck.co.uk page 12/12