




report date: 2024-03-29

**General information**

<b>Make</b>	VAUXHALL
<b>Model</b>	COMBO L1H1 2000 SPORTIVE CDTI
<b>Colour</b>	Silver
<b>Year of manufacture</b>	2017
<b>Top speed</b>	100 mph
<b>Gearbox</b>	5 speed Manual

**Engine & fuel consumption**

<b>Power</b>	95 BHP
<b>Max. torque</b>	200 Nm at 1.500 rpm
<b>Engine capacity</b>	1.248 cc
<b>Cylinders</b>	4
<b>Fuel type</b>	Diesel
<b>Consumption city</b>	43.5 mpg
<b>Consumption extra urban</b>	67.3 mpg
<b>Consumption combined</b>	56.5 mpg
<b>CO2 emission</b>	133 g/km
<b>CO2 label</b>	E






Internet history

Entry 1

Date	2021-09-26
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk





MOT history

MOT expiry date	2025-01-03
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	7

<b>MOT #6</b>	2024-01-04 17:05
<b>MOT test number</b>	906615003080
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-03
<b>Advice</b>	Offside Front Macpherson strut ball joint has slight play Top mount slight play (5.3.4 (a) (i))

<b>MOT #5</b>	2024-01-03 11:01
<b>MOT test number</b>	850274181899
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear fog lamp not working (4.5.1 (a) (ii))
<b>Fail</b>	Brake performance unable to be tested (1.2.1 (g))
<b>Fail</b>	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
<b>Fail</b>	Rear fog lamp switch inoperative (4.5.3 (a))
<b>Advice</b>	Offside Front Macpherson strut ball joint has slight play Top mount slight play (5.3.4 (a) (i))
<b>Fail</b>	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b>	Offside Front Inner Brake pad(s) incorrectly mounted (1.1.13 (c))



**MOT #4** 2022-10-17 08:37

**MOT test number** 695721170662

**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner faces/edges (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge down to 3mm tread (5.2.3 (e))

**MOT #3** 2021-10-18 07:13

**MOT test number** 943838725843

**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2** 2020-07-25 09:13

**MOT test number** 724536708055

**Result** ✓ Passed

**MOT #1** 2020-07-10 05:15

**MOT test number** 592303888725

**Result** ✓ Passed

- Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
3 January 2025

**Tax status** Valid until 1 January

**Days left** 246

**MOT expiry date** 3 January 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 320,00,-
<b>Standard rate (6 months)</b>	£ 176,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LA17RPY</b>
Plate since	2019-03-29
Current registration	<b>LA17RPY</b>
Plate since	2019-03-29

More info >



**Finance check**

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-07-18
Last registration	2024-01-04
Complete history	<a href="#">See info</a>



Registration #1	2017-07-18	29 mi
Registration #2	2020-07-25	76.970 mi
Registration #3	2021-01-20	81.277 mi
Registration #4	2021-10-18	85.545 mi
Registration #5	2022-01-20	85.277 mi
Registration #6	2022-01-20	85.277 mi
Registration #7	2024-01-04	85.277 mi

[More info >](#)



**Dimensions & weight**

<b>Width</b>	2119 mm
<b>Height</b>	1845 mm
<b>Length</b>	4390 mm
<b>Wheel base</b>	2750 mm
<b>Kerb weight</b>	1290 kg
<b>Max. allowed weight</b>	2040 kg

**Additional information**

<b>Fuel tank capacity</b>	60 l
<b>Fuel delivery</b>	Direct Injection
<b>Number of seats</b>	2
<b>Number of axles</b>	2
<b>Engine number</b>	330A10006272032 LN9