




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-01-17
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-24
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	42
Total items failed	7

MOT #16	2023-05-22 11:19
MOT test number	776650156283
Result	✓ Passed
Next expiry date	2024-05-24
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-05-22 09:39
MOT test number	101212507142
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-05-25 18:03
MOT test number	383963588744
Result	✓ Passed

**MOT #13**

2021-05-25 12:52

**MOT test number**

335894705178

**Result**

✓ Passed

**Advice** Offside Front side repater condensated - damaged**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear arm bushes splitting both sides NS and OS (5.3.4 (a) (i))**MOT #12**

2021-05-25 10:56

**MOT test number**

960872097655

**Result**

✗ Failed

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear arm bushes splitting both sides NS and OS (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front side repater condensated - damaged**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords bald on edges (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on edges (5.2.3 (e))**MOT #11**

2020-05-11 13:49

**MOT test number**

993790996148

**Result**

✓ Passed

**Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2020-05-11 08:30

**MOT test number**

876835011975

**Result****✗ Failed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge passenger side rear tyre tread worn on inner edge almost to legal limit (5.2.3 (e))

**Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tyre tread cut exposing cord (5.2.3 (d) (i))

**MOT #9**

2019-04-15 08:46

**MOT test number**

155501799442

**Result****✓ Passed**

**Advice** Offside Front tyre worn smooth on inner raised edge

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Front tyre worn smooth on inner raised edge

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #8**

2019-04-15 08:46

**MOT test number**

751248418934

**Result****✗ Failed**

**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a))

**Pass with rectification** Nearside Side repeater not working (4.4.1 (a) (ii))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Front tyre worn smooth on inner raised edge

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Front tyre worn smooth on inner raised edge

**MOT #7** 2018-04-18 08:40**MOT test number** 162578822517**Result** ✓ Passed**Advice** Nearside Front Tyre worn on raised edges**Advice** Nearside Rear Tyre worn on inner raised edge**Advice** Offside Front Tyre worn on raised edges**MOT #6** 2017-03-31 12:01**MOT test number** 443170038196**Result** ✓ Passed**Advice** Offside Rear inner of tyre stepped tread pattern**Advice** Central Front under tray fitted**MOT #5** 2016-04-08 11:23**MOT test number** 991569888966**Result** ✓ Passed**MOT #4** 2015-04-09 12:46**MOT test number** 225709595039**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f tyre has some cuts but not to cords / ply**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3**

2015-04-09 12:46

**MOT test number**

256399095088

**Result****✗ Failed****Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f tyre has some cuts but not to cords / ply**MOT #2**

2014-04-11 13:43

**MOT test number**

968991204147

**Result****✓ Passed****Notice** Front wipers smearing**Notice** Under-trays fitted obscuring some underside components**Notice** Signs off injector seal gone (not fuel)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1**

2013-04-16 14:21

**MOT test number**

398406403166

**Result****✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
24 May 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	24 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-29
Last registration	2023-05-22
Complete history	<a href="#">See info</a>



Registration #1	2010-03-29	11 mi
Registration #2	2013-04-16	47.517 mi
Registration #3	2014-04-11	54.776 mi
Registration #4	2015-04-09	60.196 mi
Registration #5	2016-04-08	63.512 mi
Registration #6	2017-03-31	67.744 mi
Registration #7	2018-04-18	78.312 mi
Registration #8	2019-04-15	92.919 mi
Registration #9	2019-04-15	92.919 mi
Registration #10	2020-05-22	95.277 mi
Registration #11	2020-05-22	95.277 mi
Registration #12	2020-05-22	95.277 mi
Registration #13	2020-05-22	95.277 mi
Registration #14	2020-05-22	95.277 mi
Registration #15	2020-05-22	95.277 mi
Registration #16	2020-05-22	95.277 mi
Registration #17	2020-05-22	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1054111