



report date: 2024-03-29

General information

Make	MINI
Model	ONE AUTO ONE
Colour	Yellow
Year of manufacture	2007
Top speed	112 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	94 BHP
Max. torque	140 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-10
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-24
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	18
Total items failed	16

MOT #23	2023-09-25 11:00
MOT test number	108658781451
Result	✓ Passed
Next expiry date	2024-09-24
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #22	2023-09-25 11:00
MOT test number	709652071650
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21	2022-09-23 14:39
MOT test number	434005973900
Result	✓ Passed

MOT #20	2022-09-14 08:26
MOT test number	262971441389
Result	✗ Failed
Fail	Exhaust emits dense blue smoke at idle (8.2.1.2 (f))

**MOT #19** 2021-09-18 11:06**MOT test number** 107322393969**Result** ✓ Passed**MOT #18** 2020-11-27 16:06**MOT test number** 298950601758**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Inner rear (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Inner rear (5.3.4 (a) (i))**MOT #17** 2020-11-25 09:57**MOT test number** 977430484956**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Inner rear (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Inner rear (5.3.4 (a) (i))

**MOT #16** 2019-11-07 09:19**MOT test number** 416209522023**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Coolant leak bad**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine rattling oil level ok**MOT #15** 2018-11-29 14:46**MOT test number** 356953824184**Result** ✓ Passed**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2017-11-30 11:52**MOT test number** 280928410615**Result** ✓ Passed**MOT #13** 2017-04-04 14:37**MOT test number** 880719882298**Result** ✓ Passed**MOT #12** 2017-04-04 14:37**MOT test number** 241888516388**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high very high (1.8)**Pass with rectification** Offside Headlamp aim too high very high (1.8)



<b>MOT #11</b>	2016-10-04 14:14
----------------	------------------

<b>MOT test number</b>	187394416810
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #10</b>	2015-10-05 10:30
----------------	------------------

<b>MOT test number</b>	349768149494
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2014-11-04 11:33
---------------	------------------

<b>MOT test number</b>	318598304308
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2014-11-01 10:27
---------------	------------------

<b>MOT test number</b>	915825604392
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

<b>MOT #7</b>	2013-10-09 12:04
---------------	------------------

<b>MOT test number</b>	198682883207
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #6** 2013-10-09 12:04**MOT test number** 556852783254**Result** ✗ Failed**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #5** 2012-09-27 14:46**MOT test number** 147161172222**Result** ✓ Passed**MOT #4** 2012-09-27 14:26**MOT test number** 398541972204**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2011-10-10 16:44**MOT test number** 947953681262**Result** ✓ Passed**Notice** Front windscreen wiper rubbers slightly torn**MOT #2** 2010-10-26 14:58**MOT test number** 463519590228**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)



MOT #1	2010-10-26 14:58
MOT test number	221369590205
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	24 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-10-20
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2007-10-20	19 mi
Registration #2	2010-10-26	7.929 mi
Registration #3	2011-10-10	9.398 mi
Registration #4	2012-09-27	12.564 mi
Registration #5	2012-09-27	12.564 mi
Registration #6	2013-10-09	19.107 mi
Registration #7	2014-11-01	29.755 mi
Registration #8	2014-11-04	29.759 mi
Registration #9	2015-10-05	34.634 mi
Registration #10	2016-10-04	40.267 mi
Registration #11	2017-04-04	42.395 mi
Registration #12	2017-04-04	42.395 mi
Registration #13	2018-09-25	55.277 mi
Registration #14	2019-09-25	55.277 mi
Registration #15	2020-09-25	55.277 mi
Registration #16	2021-09-25	55.277 mi
Registration #17	2022-09-25	55.277 mi
Registration #18	2023-09-25	55.277 mi
Registration #19	2023-09-25	55.277 mi
Registration #20	2023-09-25	55.277 mi
Registration #21	2023-09-25	55.277 mi
Registration #22	2023-09-25	55.277 mi
Registration #23	2023-09-25	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1100 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B030I073