






report date: 2024-03-29

General information

Make	VOLVO
Model	S40 SE LUX
Colour	Red
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2022-01-30

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #13	2024-02-22 11:02
MOT test number	871728839672
Result	✓ Passed
Next expiry date	2025-02-21
Advice Both front tyres wear to edges	

MOT #12	2024-02-21 17:20
MOT test number	583260739270
Result	X Failed
Fail Offside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))	
Advice Both front tyres wear to edges	

MOT #11	2023-02-20 17:46
MOT test number	736837688091
Result	✓ Passed
Advice Front tyres slight wear to edges	

MOT #10	2022-02-18 15:11
MOT test number	156624264767
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2021-07-09 15:44

MOT test number 360755664938

Result ✓ Passed

MOT #8 2021-07-09 08:16

MOT test number 120390763681

Result ★ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished and cracked. (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50/17. (5.2.3 (d) (i))

MOT #7 2021-01-26 10:50

MOT test number 756521332354

Result ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #6 2020-01-18 11:16

MOT test number 845380854117

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-01-23 10:15

MOT test number 333842088494

Result

Passed

Advice Offside Rear tyre wearing on inner edge of tread

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4	2018-01-05 14:47
MOT test number	156326615704
Result	✓ Passed
MOT #3	2017-01-10 09:15
MOT test number	822026107350
Result	✓ Passed
MOT #2	2016-01-13 11:11
MOT test number	696588339843
Result	✓ Passed
MOT #1	2015-01-21 16:09
MOT test number	577761925076
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manus .	

2000000	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK SIFE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



VE61UOT report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-26
Last registration	2024-02-22
Complete history	See info



Registration #1	2012-01-26	20 mi
Registration #2	2015-01-21	15.455 mi
Registration #3	2016-01-13	20.693 mi
Registration #4	2017-01-10	25.949 mi
Registration #5	2018-01-05	33.299 mi
Registration #6	2019-01-23	39.183 mi
Registration #7	2020-01-18	44.690 mi
Registration #8	2021-01-26	50.076 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



VE61UOT report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/1.

Engine number

1068698