





report date: 2024-03-29

General information

Make	AUDI
Model	A2 TDI
Colour	Blue
Year of manufacture	2001
Top speed	107 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	195 Nm at 2.200 rpm
Engine capacity	1.390 сс
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	78.5 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/15



Internet history

Entry 3

Date 2021-11-28

Pictures 12

Listing price View report









source: cargurus.co.uk

Entry 2

Date 2021-08-03

Pictures 39

Listing price View report









source: yesauto.com

Entry 1

Date 2021-01-27

Pictures 10

Listing price View report









source: autoonline.co.uk

CarCheck.co.uk page 2/15



Μ	OT	his	tory

MOT expiry date	2024-11-08
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	29
Total items failed	13

MOT #24	2023-11-09 17:11
MOT test number	101180760217
Result	✓ Passed
Next expiry date	2024-11-08

MOT #23	2023-11-09 12:41
MOT test number	846532897444
Result	X Failed
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	

MOT #22	2022-12-07 16:57
MOT test number	817408397713
Result	✓ Passed

MOT #21	2022-12-06 16:03
MOT test number	846522996094
Result	X Failed
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

page 3/15 CarCheck.co.uk



MOT #20 2021-12-17 15:15

MOT test number 920115690463

Result \rightarrow Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19 2021-12-16 16:46

MOT test number 647308281922

Result X Failed

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #18 2019-07-31 11:44

MOT test number 431948119499

Result \(\sqrt{Passed} \)

MOT #17 2019-07-31 11:44

MOT test number 581358614751

Result X Failed

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all

lamps (4.7.1 (b) (ii))

Pass with rectification Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #16

MOT test number

Result

Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Side repeater insecure (4.4.1 (c) (i))

Minor

Nearside Registration plate lamp insecure (4.7.1 (c) (i))

MOT #15 2018-09-15 08:33 **MOT** test number 779893596201 Result × Failed Minor Offside Side repeater insecure (4.4.1 (c) (i)) Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the Fail ingress of dirt (6.1.7 (g) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i)) Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) **Advice**

MOT #14

MOT test number

Result

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/15



MOT #13 2017-09-12 16:27

MOT test number 688418661176

Result X Failed

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Rear Nail in tyre

MOT #12 2016-09-10 15:11

MOT test number 343152298870

Result \square Passed

MOT #11 2016-09-10 14:05

MOT test number 835916466781

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10 2015-09-12 09:14

MOT test number 626283391545

Result

Passed

MOT #9 2014-09-12 12:38

MOT test number 886055654227

Result ✓ Passed

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

Notice Nearside rear tyre in poor condition

(2.5.C.1a)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 6/15



MOT #8

WJ51NEF report date: 2024-03-29

2013-09-16 11:34

MOT test number 467439453296

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #7 2012-09-17 10:59

MOT test number 899701662266

Result \(\sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #6 2011-08-31 14:20

MOT test number 949053941273

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2010-08-31 16:33

MOT test number 762323340280

Result

✓ Passed

MOT #4 2009-08-24 17:39

MOT test number 974436339259

Advice Offside Front brake disc slightly pitted (3.5.1h)

Advice Nearside Front brake disc slightly pitted (3.5.1h)

CarCheck.co.uk page 7/15



MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Off side and near side front tyres worn on edges very close to limit!

MOT #2		2007-08-09 09:33
MOT test	number	730861627299
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front tyres worn on edges	

MOT #1	2006-08-08 09:50
MOT test number	322270926232
Result	✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax expired: 1 December 2022



Expires: 8 November 2024

Tax status	Expired at 1 December 2022
Days left	515 days too late
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



_	
~	history
IMMAR	

For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		/e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2001-09-01
Last registration	2023-11-09
Complete history	See info



Registration #1	2001-09-01	6 mi
Registration #2	2006-08-08	19.585 mi
Registration #3	2007-08-09	22.695 mi
Registration #4	2008-08-11	25.556 mi
Registration #5	2009-08-24	30.123 mi
Registration #6	2010-08-31	39.673 mi
Registration #7	2011-08-31	49.160 mi
Registration #8	2012-09-17	59.980 mi
Registration #9	2013-09-16	70.290 mi
Registration #10	2014-09-12	80.381 mi
Registration #11	2015-09-12	90.383 mi
Registration #12	2016-09-10	101.825 mi
Registration #13	2016-09-10	101.825 mi
Registration #14	2017-09-12	111.198 mi
Registration #15		9.79 ss
Registration #16		11.777 es
Registration #17		0.77 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.77 44
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 14/15

Registration #27

Registration #28

More info >

mn.n.n



Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

		_		
Dim	ensior	יכ צי	MAIG	ht
ווווט	CHOIDE	IS CX	WCIU	IIIL

Width	1890 mm
Height	1553 mm
Length	3826 mm
Wheel base	2405 mm
Kerb weight	990 kg

Additional information

Fuel tank capacity	34 I
Fuel delivery	Direct Injection
Number of doors	5
Engine number	AMF 091975

CarCheck.co.uk page 15/15