



PEUGEOT



GW55GVO

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Black
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-05
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-23
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	30
Total items failed	7

MOT #16 2020-11-24 09:09

MOT test number 246235757623

Result ✓ Passed

Next expiry date 2021-11-23

Advice Play in steering rack inner joint(s) Both N/S and O/S

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15 2020-11-24 08:46

MOT test number 926716383623

Result ✗ Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Play in steering rack inner joint(s) Both N/S and O/S

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #14**

2019-11-22 09:01

MOT test number

848919442777

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2018-11-22 17:29

MOT test number

683569498176

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2017-11-04 11:16

MOT test number

247426064397

Result

✓ Passed

**MOT #11** 2016-11-28 10:38**MOT test number** 675888964335**Result** ✓ Passed**MOT #10** 2015-12-10 17:35**MOT test number** 878836675053**Result** ✓ Passed**Advice** Rear tyres perished**MOT #9** 2015-12-10 09:10**MOT test number** 193119728731**Result** ✗ Failed**Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)**Advice** Rear tyres perished**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #8** 2014-12-03 09:21**MOT test number** 986057934360**Result** ✓ Passed**Notice** Rear exhaust bracket broken but the exhaust system is still adequately supported**Notice** Nearside rear tyre perishing**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre perishing

**MOT #7** 2013-12-03 10:48**MOT test number** 187497233310**Result** ✓ Passed**Notice** Rear exhaust bracket broken but exhaust still supported.**MOT #6** 2012-12-05 11:29**MOT test number** 296620442382**Result** ✓ Passed**MOT #5** 2011-12-09 09:24**MOT test number** 538763941354**Result** ✓ Passed**Notice** Front brake discs worn**Notice** Nearside front tyre worn on outer edge**MOT #4** 2011-12-09 09:24**MOT test number** 745993841383**Result** ✗ Failed**Notice** Front brake discs worn**Pass with rectification** Rear fog lamp not working (1.3.2b)**Notice** Nearside front tyre worn on outer edge**MOT #3** 2011-01-14 11:30**MOT test number** 329694211023**Result** ✓ Passed**Notice** N\front tyre worn on outer edge**Notice** Front brake disc's worn



MOT #2	2010-01-14 15:04
MOT test number	714484110031
Result	✓ Passed

MOT #1	2009-01-09 13:36
MOT test number	120859809011
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	GW55GVO
Plate since	2019-09-28
Current registration	GW55GVO
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-01-17
Last registration	2020-11-24
Complete history	See info



Registration #1	2006-01-17	9 mi
Registration #2	2009-01-09	17.107 mi
Registration #3	2010-01-14	20.824 mi
Registration #4	2011-01-14	24.892 mi
Registration #5	2011-12-09	30.408 mi
Registration #6	2012-12-05	39.099 mi
Registration #7	2013-12-03	44.209 mi
Registration #8	2014-12-03	46.999 mi
Registration #9	2015-12-10	50.923 mi
Registration #10	2016-01-01	51.377 mi
Registration #11	2016-01-01	51.377 mi
Registration #12	2016-01-01	51.377 mi
Registration #13	2016-01-01	51.377 mi
Registration #14	2016-01-01	51.377 mi
Registration #15	2016-01-01	51.377 mi
Registration #16	2016-01-01	51.377 mi
Registration #17	2016-01-01	51.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST65298536