





report date: 2024-03-29

### General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

## Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-12-31

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-31
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #17	2024-01-17 12:54
MOT test number	659625249503
Result	<b>✓</b> Passed
Next expiry date	2025-01-31
Advice Rear Passenger seat(s) missing at time of test	

MOT #16	2023-02-01 15:09
MOT test number	214639489734
Result	<b>✓</b> Passed
Advice Nearside Rear Passenger seat(s) missing at time of test	

MOT #15	2022-12-20 16:01
MOT test number	254686268928
Result	<b>×</b> Failed
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Rear Seat belt not functioning as intended centre jammed (7.1.2 (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2021-12-30 17:23
MOT test number	945402614605
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13	2021-05-21 13:28
MOT test number	475257208019
Result	<b>✓</b> Passed
MOT #12	2020-05-29 12:30
MOT test number	813876311020
Result	✓ Passed

MOT #11	20	)19-05-11 08:57
MOT test	number	677394763417
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3	3.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #10		2018-05-11 11:17
MOT test	number	592283916661
Result		✓ Passed
<b>Advice</b> (8.3.1d)	Nearside Front Windscreen has damage to an area less than a 40mm circle outs	side zone 'A'
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT** #9 2018-05-11 11:17 776164043020 **MOT** test number Result × Failed **Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Pass with rectification Nearside Front Headlamp aim too far to the left adjusted during test (1.8) **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number
997823401908

Result
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

Result

Advice Rear suspension showing signs of corrosion.

Advice Slight play in steering rack.

 MOT #6
 2015-05-18 16:20

 MOT test number
 405588635103

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

**MOT #5** 2014-06-04 15:01 **MOT** test number 127685254169 Result ✓ Passed **MOT #4** 2014-05-31 09:17 **MOT test number** 496011354157 Result × Failed **Notice** Under-trays fitted obscuring some underside components Fail Offside Rear coil spring broken (2.4.C.1a) Notice Engine covers fitted obscuring some components in the engine bay

MOT #3

MOT test number

639700353189

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

Result

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Notice Under trays fitted

CarCheck.co.uk page 6/13



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	31 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full reports are considered to the current and see all owner registrations.	
***************************************	
**********	
***************************************	
**************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-31
Last registration	2024-01-17
Complete history	See info



Registration #1	2008-03-31	16 mi
Registration #2	2011-03-01	29.915 mi
Registration #3	2012-06-25	39.564 mi
Registration #4	2013-05-30	41.788 mi
Registration #5	2014-05-31	44.754 mi
Registration #6	2014-06-04	44.787 mi
Registration #7	2015-05-18	46.874 mi
Registration #8	2016-05-21	58.790 mi
Registration #9	2017-05-13	70.656 mi
Registration #10	2018-05-11	77.163 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D.277 es

More info >

CarCheck.co.uk page 12/13



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

## Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG

CarCheck.co.uk page 13/13