





report date: 2024-03-28

# General information

Make	MERCEDES-BENZ	
Model	CLA CLA220 CDI AMG SPORT	
Colour	Grey	
Year of manufacture	2015	
Top speed	143 mph	
0 - 100 km/h	8.2 seconds	
0 - 60 mph	8.2 seconds	
Gearbox	7 speed automatic	

# Engine & fuel consumption

Power	130 kW / 177 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



# Internet history

# Entry 1

Date 2021-10-28


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT	history
1.101	iliocol y

MOT expiry date	2024-07-24
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #7	2023-07-21 15:38
MOT test number	789541637662
Result	<b>✓</b> Passed
Next expiry date	2024-07-24
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2022-07-20 14:01
MOT test number	812725240205
Result	<b>✓</b> Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))  Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT #5** 2021-07-23 12:42

**MOT test number** 210944619211

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge 2-3mm 225/40R18 (5.2.3 (e))

**Advice** Central Rear exhaust heat shield insecure

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 225/40R18 (5.2.3 (d) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge 2-3mm 225/40R18 (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 225/40R18 (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2020-07-08 11:08

**MOT test number** 582493567676

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-07-25 09:55

MOT test number 138694220399

**Result** 
✓ Passed

MOT #2 2018-09-21 13:13

**MOT test number** 236082540886

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



**MOT #1** 2017-09-25 10:01

**MOT test number** 138332012076

**Result** ✓ Passed

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

# Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	
*********	
***************************************	
********	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 9/12



## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-05-07
Last registration	2023-07-21
Complete history	See info



Registration #1	2015-05-07	28 mi
Registration #2	2017-09-25	47.446 mi
Registration #3	2018-09-21	56.721 mi
Registration #4	2019-07-25	64.009 mi
Registration #5	2020-07-08	76.133 mi
Registration #6		11.117 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		10.777 au

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	
View the complete MERCENES PENZ factory list for this	
View the complete MERCEDES-BENZ factory list for this vehicle here.	More info >

# Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack co. uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	65193032710771