



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-25
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-02
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	31
Total items failed	6

MOT #13	2023-08-26 08:26
MOT test number	245291891302
Result	✓ Passed
Next expiry date	2024-09-02
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Gearbox mounting defective

MOT #12	2023-08-26 08:26
MOT test number	952039538538
Result	✗ Failed
Pass with rectification	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Pass with rectification	Reversing lamp does not emit a steady white light (4.6.2 (a))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Rear Gearbox mounting defective

**MOT #11** 2022-09-03 12:45**MOT test number** 891057408996**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2022-09-03 11:59**MOT test number** 453480982373**Result** ✗ Failed**Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))**MOT #9** 2021-09-03 09:57**MOT test number** 859237039581**Result** ✓ Passed**MOT #8** 2021-09-02 10:10**MOT test number** 401461394154**Result** ✗ Failed**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #7** 2021-03-27 10:39**MOT test number** 888560398933**Result** ✓ Passed**MOT #6** 2020-03-26 17:25**MOT test number** 661199113014**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre worn out on inner edge/tread-Tyre size 235/55R19 104Y (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn out on inner edge/tread-Tyre size 235/55R19 104Y (5.2.3 (e))

MOT #5 2019-03-29 10:33**MOT test number** 965770237097**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-03-29 09:19**MOT test number** 258548692395**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit inside edge (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit inside edge (4.1.E.1)

**MOT #3** 2017-03-28 14:10**MOT test number** 935200987656**Result** ✓ Passed

- Advice** Nearside front tyre worn on edges
- Advice** Oil leak
- Advice** Offside front tyre worn on inner edge
- Advice** Rear wiper blade worn out
- Advice** Rear brake pads worn
- Advice** Rear tyres worn on edges

MOT #2 2017-03-28 08:36**MOT test number** 946191968643**Result** ✗ Failed

- Advice** Offside front tyre worn on inner edge
- Advice** Rear wiper blade worn out
- Advice** Rear brake pads worn
- Advice** Rear tyres worn on edges
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Advice** Nearside front tyre worn on edges
- Advice** Oil leak

MOT #1 2016-03-29 13:24**MOT test number** 345062305794**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-28
Current registration	 VAUXH
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-30
Last registration	2023-08-26
Complete history	See info



Registration #1	2013-03-30	24 mi
Registration #2	2016-03-29	14.987 mi
Registration #3	2017-03-28	18.921 mi
Registration #4	2017-03-28	18.921 mi
Registration #5	2018-03-29	24.706 mi
Registration #6	2019-03-29	31.977 mi
Registration #7	2020-03-26	37.070 mi
Registration #8	2021-03-27	39.028 mi
Registration #9	2022-03-27	39.028 mi
Registration #10	2022-03-27	39.028 mi
Registration #11	2022-03-27	39.028 mi
Registration #12	2022-03-27	39.028 mi
Registration #13	2022-03-27	39.028 mi
Registration #14	2022-03-27	39.028 mi
Registration #15	2022-03-27	39.028 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ