





report date: 2024-03-28

## General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Blue
Year of manufacture	2007
Top speed	132 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	223 Nm at 4.500 rpm
Engine capacity	2.354 сс
Cylinders	4
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.2 mpg
CO2 emission	237 g/km
CO2 label	L



CarCheck.co.uk page 1/14



## Internet history

## Entry 2

Date 2021-06-27

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-06-26


Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-02-26
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	32
Total items failed	1

MOT #18		2024-02-26 09:08
MOT test	number	969676574197
Result		✓ Passed
Next expi	ry date	2025-02-26
Advice	Oil leak, but not excessive Power steering (8.4.1 (a) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exces	sive movement (5.3.4 (a)
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4

MOT #17		2023-02-27 13:15
MOT test	number	162474241687
Result		✓ Passed
Advice	Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #16	2022-02-24 10:33
MOT test number	208766312092
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



**MOT #15** 2021-02-17 08:40

MOT test number 479858196302

**Result** ✓ Passed

Minor

Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

**MOT #14** 2021-02-16 11:54

MOT test number 431274732218

Result × Failed

**DANGEROUS** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Minor Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

MAJOR Offside Rear Lower Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Nearside Rear Lower Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Rear Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-02-13 13:11

**MOT test number** 805350981410

**Result** ✓ Passed

**MOT #12** 2020-02-13 12:37

MOT test number 656587091234

Result X Failed

**MAJOR** Nearside Front Bumper insecure (6.1.4 (a) (i))

CarCheck.co.uk page 4/14



MOT #11 2019-02-19 14:53

**MOT test number** 731513800880

**Result** ✓ Passed

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2018-02-12 15:59

**MOT test number** 722589036457

Result \( \sqrt{Passed} \)

MOT #9 2017-02-17 10:43

**MOT test number** 567814091953

**Result** 
✓ Passed

Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**Advice** Brake pedal anti slip rubber wearing

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2017-02-17 10:04

MOT test number 315863142603

Result X Failed

Advice Brake pedal anti slip rubber wearing

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 5/14



MOT test number

Result

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2015-01-14 11:49
MOT test number	178974115070
Result	<b>✓</b> Passed
MOT #5	2014-04-10 12:25
MOT test number	665120504175
Result	<b>✓</b> Passed
Notice Items removed from driver's view prior to test	

MOT #4	2013-04-09 17:22
MOT test number	525659993034
Result	✓ Passed

MOT #3	2012-04-10 09:45
MOT test number	545171802193
Result	<b>✓</b> Passed

MOT #2		2011-04-11 12:17
MOT test	number	968671701142
Result		✓ Passed
Advice Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)  Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



MOT #1 2010-04-14 15:50

**MOT test number** 483154500187

**Result** ✓ Passed

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	26 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
*********	
*********	
Plate changes	More info >
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	UK ZIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-19
Last registration	2024-02-26
Complete history	See info



Registration #1	2007-04-19	18 mi
Registration #2	2010-04-14	13.027 mi
Registration #3	2011-04-11	16.346 mi
Registration #4	2012-04-10	19.785 mi
Registration #5	2013-04-09	22.969 mi
Registration #6	2014-04-10	29.147 mi
Registration #7	2015-01-14	32.515 mi
Registration #8	2016-02-18	39.242 mi
Registration #9	2017-02-17	43.432 mi
Registration #10	2017-02-17	43.432 mi
Registration #11	2018-02-12	47.570 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 es

More info >

page 13/14 CarCheck.co.uk



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1760 mm
Height	1495 mm
Length	4750 mm
Wheel base	2720 mm
Kerb weight	1554 kg

## Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	K24A35500257

CarCheck.co.uk page 14/14