



report date: 2024-03-28

General information

| | |
|---------------------|-------------------------------------|
| Make | AUDI |
| Model | A7 TDI QUATTRO S LINE BLACK EDITION |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 155 mph |
| 0 - 100 km/h | 5.3 seconds |
| 0 - 60 mph | 5.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 230 kW / 313 HP / 309 BHP |
| Max. torque | 650 Nm at 1.450 rpm |
| Engine capacity | 2.967 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 166 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-03-19 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-21 |
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 18 |
| Total items failed | 3 |

| | |
|------------------|---|
| MOT #10 | 2024-01-22 16:01 |
| MOT test number | 948153953016 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-21 |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Front Child Seat fitted not allowing full inspection of adult belt |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |

| | |
|-----------------|---|
| MOT #9 | 2024-01-18 14:22 |
| MOT test number | 958914892678 |
| Result | ✗ Failed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Fail | Offside Front Service brake grabbing severely (1.2.1 (c)) |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Front Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

**MOT #8** 2023-01-20 10:59**MOT test number** 426014877403**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7 2022-01-10 12:10**MOT test number** 663225813606**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2021-01-22 17:38**MOT test number** 741501218117**Result** ✓ Passed

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2021-01-21 16:07**MOT test number** 951208134089**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))



MOT #4 2020-01-11 15:34

MOT test number 762922827456

Result ✓ Passed

MOT #3 2020-01-11 14:12

MOT test number 784810268110

Result ✗ Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #2 2018-09-05 10:12

MOT test number 439000680349

Result ✓ Passed

MOT #1 2017-08-31 15:26

MOT test number 790260014685

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
21 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 3 |
| MOT expiry date | 21 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BK64LFP |
| Plate since | 2024-03-28 |
| Current registration | BK64LFP |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2014-09-16 |
| Last registration | 2024-01-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-09-16 | 23 mi |
| Registration #2 | 2017-08-31 | 33.139 mi |
| Registration #3 | 2018-09-05 | 37.810 mi |
| Registration #4 | 2020-01-11 | 44.939 mi |
| Registration #5 | 2020-01-11 | 44.945 mi |
| Registration #6 | 2021-01-21 | 48.519 mi |
| Registration #7 | 2022-01-22 | 51.277 mi |
| Registration #8 | 2022-01-22 | 51.277 mi |
| Registration #9 | 2022-01-22 | 51.277 mi |
| Registration #10 | 2022-01-22 | 51.277 mi |
| Registration #11 | 2022-01-22 | 51.277 mi |
| Registration #12 | 2024-01-22 | 51.277 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 2139 mm |
| Height | 1420 mm |
| Length | 4969 mm |
| Wheel base | 2914 mm |
| Kerb weight | 1850 kg |
| Max. allowed weight | 2460 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 65 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | CGQB055976 |