



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2015
Top speed	116 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	121 g/km
CO2 label	D






Internet history

Entry 2

Date	2023-12-14
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2022-04-29
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #9	2024-04-26 09:33
--------	------------------

MOT test number	379774555208
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-05-08
------------------	------------

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))



MOT #8	2024-04-26 07:59
MOT test number	536845986602
Result	✗ Failed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2023-04-13 11:31
MOT test number	596997581009
Result	✓ Passed
MOT #6	2022-05-09 15:29
MOT test number	990402831686
Result	✓ Passed

**MOT #5**

2022-05-07 10:24

MOT test number

570955642656

Result**✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))

MOT #4

2021-07-08 11:41

MOT test number

743501950727

Result**✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside rear tyres cracked / perished (5.2.3 (d) (ii))

MOT #3

2020-07-13 08:43

MOT test number

892772820061

Result**✓ Passed**

- Advice** Both front tyres starting to wear low
- Advice** Both rear tyres perished / starting to crack

MOT #2

2019-07-18 11:59

MOT test number

843204694608

Result**✓ Passed**



MOT #1	2018-06-19 14:43
MOT test number	330799486230
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 May 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RE15XEV
Plate since	2024-03-29
Current registration	 RE15XEV
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-03
Last registration	2024-04-26
Complete history	See info



Registration #1	2015-07-03	10 mi
Registration #2	2018-06-19	44.814 mi
Registration #3	2019-07-18	58.183 mi
Registration #4	2020-07-13	63.475 mi
Registration #5	2021-07-08	69.163 mi
Registration #6	2022-05-20	75.277 mi
Registration #7	2023-05-20	81.277 mi
Registration #8	2023-05-20	87.277 mi
Registration #9	2023-05-20	93.277 mi
Registration #10	2023-05-20	99.277 mi
Registration #11	2024-04-26	105.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1674 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1490 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CAYCAY0859