



PEUGEOT

MT58UCP

report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Grey
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg





MOT history

MOT #20 2023-12-20 09:55

MOT test number 914422139995

Result ✓ Passed

Next expiry date 2024-12-21

- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Alternator belt badly cracked
- Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Nearside Rear Nail in tyre
- Advice

Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #19**

2023-12-18 14:50

**MOT test number**

893845221839

**Result****✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Inner Steering linkage ball joint has excessive play rack (2.1.3 (b) (i))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Alternator belt badly cracked
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Nail in tyre
- Fail** Emissions unable to be completed insufficient oil in engine (8.2.1.2 (d))
- Fail** Offside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**MOT #18** 2022-12-22 12:58**MOT test number** 727665979059**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside front headlamp has slight crack**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside front outer cv gaiter has slight pin hole**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #17** 2022-12-22 12:58**MOT test number** 705956499475**Result** ✗ Failed**Advice** Nearside Front Nail in tyre**Advice** Offside front headlamp has slight crack**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside front outer cv gaiter has slight pin hole**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #16** 2021-12-11 16:32**MOT test number** 320344230331**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #15** 2021-12-11 16:32**MOT test number** 941007248221**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too far to the left (4.1.2 (a))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2020-12-10 16:43**MOT test number** 490730596568**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13** 2019-12-11 08:16**MOT test number** 878226293368**Result** ✓ Passed**MOT #12** 2019-12-07 12:34**MOT test number** 684665570364**Result** ✗ Failed**Fail** Nearside Inner Track rod end ball joint has excessive play track rod worn (2.1.3 (b) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2018-12-17 09:28**MOT test number** 176806907893**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #10** 2018-12-15 11:43**MOT test number** 753358253625**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #9** 2017-12-16 10:00**MOT test number** 931407508607**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2016-12-12 16:16**MOT test number** 118137015883**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)**MOT #7** 2016-12-12 11:27**MOT test number** 476670719304**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Play in steering rack inner joint(s)**Advice** Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-12-15 09:05**MOT test number** 585700702985**Result** ✓ Passed**Advice** Nearside and offside steering arm slight play**MOT #5** 2014-12-09 11:35**MOT test number** 227473444304**Result** ✓ Passed**MOT #4** 2013-12-06 15:01**MOT test number** 495470343458**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2013-12-06 10:04**MOT test number** 436880443365**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2013-01-04 10:19**MOT test number** 578384403088**Result** ✓ Passed**MOT #1** 2012-01-03 12:25**MOT test number** 199513202084**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-31
Last registration	2023-12-20
Complete history	<a href="#">See info</a>



Registration #1	2009-01-31	11 mi
Registration #2	2012-01-03	21.552 mi
Registration #3	2013-01-04	29.793 mi
Registration #4	2013-12-06	34.666 mi
Registration #5	2013-12-06	34.666 mi
Registration #6	2014-12-09	39.525 mi
Registration #7	2015-12-15	44.615 mi
Registration #8	2016-12-12	50.966 mi
Registration #9	2016-12-12	50.967 mi
Registration #10	2017-12-16	56.568 mi
Registration #11	2018-12-15	61.838 mi
Registration #12	2019-12-20	66.108 mi
Registration #13	2020-12-20	70.378 mi
Registration #14	2021-12-20	74.648 mi
Registration #15	2022-12-20	78.918 mi
Registration #16	2023-12-20	83.188 mi
Registration #17	2023-12-20	83.188 mi
Registration #18	2023-12-20	83.188 mi
Registration #19	2023-12-20	83.188 mi
Registration #20	2023-12-20	83.188 mi
Registration #21	2023-12-20	83.188 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST65980657