



report date: 2024-03-28

## General information

Make	VOLVO
Model	S60 D5 ES
Colour	Gold
Year of manufacture	2011
Top speed	143 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-05-01
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	18
Total items failed	11

MOT #15	2023-05-02 11:35
MOT test number	355797726025
Result	✓ Passed
Next expiry date	2024-05-01

MOT #14	2023-04-27 12:37
MOT test number	723768557842
Result	✗ Failed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13	2022-04-25 13:15
MOT test number	617710404864
Result	✓ Passed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing nail in tyre (5.2.3 (d) (ii))

**MOT #12** 2021-10-22 07:44**MOT test number** 303427663866**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre 2 x nail in tyre**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2021-10-21 13:45**MOT test number** 991399467458**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Nearside Rear Nail in tyre 2 x nail in tyre**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2020-09-11 11:58**MOT test number** 907461876981**Result** ✓ Passed**MOT #9** 2020-09-07 18:39**MOT test number** 842836890558**Result** ✗ Failed**Fail** Front Exhaust silencer insecure (8.1.1 (b) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Macpherson strut ball joint excessively worn (5.3.4 (a) (i))



<b>MOT #8</b>	2019-12-16 11:10
<b>MOT test number</b>	402032532124
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Coil spring corroded Nearside and offside (5.3.1 (b) (i))

<b>MOT #7</b>	2019-12-16 11:10
<b>MOT test number</b>	146506434069
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Coil spring corroded Nearside and offside (5.3.1 (b) (i))
<b>Pass with rectification</b>	Electronic braking system warning device inoperative (1.7 (a))
<b>Pass with rectification</b>	Nearside Rear Shock absorbers insecurely attached (5.3.2 (a) (i))
<b>Pass with rectification</b>	Electronic stability control warning lamp indicates a fault (7.12 (e))

<b>MOT #6</b>	2018-12-21 17:46
<b>MOT test number</b>	207731874720
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre slightly damaged visible runflat damage (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

<b>MOT #5</b>	2017-12-20 12:25
<b>MOT test number</b>	782779974802
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
<b>Advice</b>	Front wipers minor smearing
<b>Advice</b>	Nearside Rear Nail in tyre

**MOT #4** 2016-12-30 16:28**MOT test number** 101250440111**Result** ✓ Passed**MOT #3** 2016-12-30 10:14**MOT test number** 996310231121**Result** ✗ Failed**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #2** 2015-11-23 09:19**MOT test number** 867165483547**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin BOTH (3.5.1g)**Advice** Front Brake pad(s) wearing thin BOTH (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-11-14 10:40**MOT test number** 898968514316**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
1 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	1 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-28
Current registration	*****
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-11-25
Last registration	2023-05-02
Complete history	<a href="#">See info</a>



Registration #1	2011-11-25	27 mi
Registration #2	2014-11-14	38.665 mi
Registration #3	2015-11-23	49.871 mi
Registration #4	2016-12-30	64.503 mi
Registration #5	2016-12-30	64.522 mi
Registration #6	2017-12-20	79.479 mi
Registration #7	2018-12-21	94.863 mi
Registration #8	2019-12-16	101.663 mi
Registration #9	2019-12-16	101.663 mi
Registration #10	2020-05-20	101.663 mi
Registration #11	2020-05-20	101.663 mi
Registration #12	2020-05-20	101.663 mi
Registration #13	2020-05-20	101.663 mi
Registration #14	2020-05-20	101.663 mi
Registration #15	2020-05-20	101.663 mi
Registration #16	2020-05-20	101.663 mi
Registration #17	2020-05-20	101.663 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1613 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1006321