



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO GHIA X
Colour	Black
Year of manufacture	2004
Top speed	121 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg



LABEL UNKNOWN



MOT history

MOT #19 2022-06-01 10:13

MOT test number 872881774354

Result ✓ Passed

Next expiry date 2023-06-25

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front steering rack arm slight play

**MOT #18**

2022-05-12 15:48

MOT test number

240238223376

Result**✗ Failed**

MAJOR Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength arm corroded (5.3.6 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside front tyre balding on inner edge advise replacing

MAJOR Rear Exhaust silencer insecure (8.1.1 (b) (i))

MAJOR Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

DANGEROUS Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))

MAJOR Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Rear Registration plate does not conform to the specified requirements (0.1 (d))

Advice Nearside Rear Suspension arm damaged but not seriously weakened trailing arm bent (5.3.3 (b) (i))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MAJOR Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Rear Exhaust system insecure (6.1.2 (a))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #17**

2021-06-14 10:49

MOT test number

171505496169

Result

✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16

2020-06-26 13:01

MOT test number

469993639316

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material all around (1.1.11 (c))
- Advice** Front Exhaust has a minor leak of exhaust gases flex (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened and rear (1.1.14 (a) (ii))

MOT #15

2019-09-07 14:21

MOT test number

211093267603

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2018-09-08 14:24

MOT test number

294546616605

Result

✓ Passed

- Advice** Offside Rear Lower Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13** 2017-09-11 12:12**MOT test number** 550457597090**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2016-08-11 12:16**MOT test number** 800069355972**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2015-08-13 12:32**MOT test number** 807095125207**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-07-17 12:46**MOT test number** 226148794498**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #9** 2013-08-16 12:13**MOT test number** 365488023249**Result** ✓ Passed

**MOT #8** 2012-09-28 13:34**MOT test number** 319452672427**Result** ✓ Passed**MOT #7** 2011-10-12 13:45**MOT test number** 676585581210**Result** ✓ Passed**MOT #6** 2011-10-12 13:45**MOT test number** 549565081261**Result** ✗ Failed**Pass with rectification** Nearside Side repeater incorrect colour (1.4.A.2f)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)**MOT #5** 2010-10-14 10:15**MOT test number** 101327880293**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2009-10-01 15:55**MOT test number** 620154079224**Result** ✓ Passed**MOT #3** 2008-10-21 13:52**MOT test number** 644075298278**Result** ✓ Passed



MOT #2	2007-10-15 12:28
MOT test number	361788387249
Result	✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1	2007-10-15 12:28
MOT test number	830768087292
Result	✗ Failed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-10-15
Last registration	2022-06-01
Complete history	See info



Registration #1	2004-10-15	19 mi
Registration #2	2007-10-15	28.733 mi
Registration #3	2008-10-21	34.436 mi
Registration #4	2009-10-01	40.039 mi
Registration #5	2010-10-14	45.708 mi
Registration #6	2011-10-12	52.124 mi
Registration #7	2012-09-28	56.810 mi
Registration #8	2013-08-16	61.286 mi
Registration #9	2014-07-17	70.884 mi
Registration #10	2015-06-22	81.377 mi
Registration #11	2016-06-22	91.377 mi
Registration #12	2017-06-22	101.377 mi
Registration #13	2018-06-22	111.377 mi
Registration #14	2019-06-22	121.377 mi
Registration #15	2020-06-22	131.377 mi
Registration #16	2021-06-22	141.377 mi
Registration #17	2022-06-01	151.377 mi
Registration #18	2023-06-22	161.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1931 mm
Height	1441 mm
Length	4804 mm
Wheel base	2754 mm
Kerb weight	1615 kg
Max. allowed weight	2235 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4L49954