



report date: 2024-03-29

## General information

|                     |                   |
|---------------------|-------------------|
| Make                | VOLVO             |
| Model               | XC90 D5 SE AWD    |
| Colour              | Black             |
| Year of manufacture | 2008              |
| Top speed           | 118 mph           |
| 0 - 60 mph          | 11.1 seconds      |
| Gearbox             | 6 speed automatic |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 185 BHP             |
| Max. torque             | 400 Nm at 2.000 rpm |
| Engine capacity         | 2.401 cc            |
| Cylinders               | 5                   |
| Fuel type               | Diesel              |
| Consumption city        | 25.5 mpg            |
| Consumption extra urban | 40.4 mpg            |
| Consumption combined    | 33.2 mpg            |
| CO2 emission            | 224 g/km            |
| CO2 label               | K                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-08                  |
| Pictures      | 29                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2024-12-01 |
| <b>MOT pass rate</b>      | 81 %       |
| <b>MOT passed</b>         | 13         |
| <b>Failed MOT tests</b>   | 3          |
| <b>Total advice items</b> | 16         |
| <b>Total items failed</b> | 8          |

|                         |                  |
|-------------------------|------------------|
| <b>MOT #16</b>          | 2023-11-30 16:47 |
| <b>MOT test number</b>  | 366924818203     |
| <b>Result</b>           | ✓ Passed         |
| <b>Next expiry date</b> | 2024-12-01       |

|                        |                                                                                                                                |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------|
| <b>MOT #15</b>         | 2022-11-29 15:07                                                                                                               |
| <b>MOT test number</b> | 824025066377                                                                                                                   |
| <b>Result</b>          | ✓ Passed                                                                                                                       |
| <b>Advice</b>          | Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #14</b>         | 2021-12-01 17:12 |
| <b>MOT test number</b> | 169125422138     |
| <b>Result</b>          | ✓ Passed         |

|                        |                                                                      |
|------------------------|----------------------------------------------------------------------|
| <b>MOT #13</b>         | 2020-12-01 09:49                                                     |
| <b>MOT test number</b> | 197503094091                                                         |
| <b>Result</b>          | ✓ Passed                                                             |
| <b>Advice</b>          | Offside Front Play in steering rack inner joint(s)                   |
| <b>Advice</b>          | Nearside Front Play in steering rack inner joint(s)                  |
| <b>Advice</b>          | Oil leak, but not excessive (8.4.1 (a) (i))                          |
| <b>Advice</b>          | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #12** 2019-12-02 12:29**MOT test number** 697828971733**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-11-27 10:10**MOT test number** 660396979771**Result** ✗ Failed**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #10** 2018-08-16 09:35**MOT test number** 310501118484**Result** ✓ Passed**MOT #9** 2017-08-18 14:47**MOT test number** 446639681942**Result** ✓ Passed**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush Front of joint (2.5.A.1c)

**MOT #8** 2017-08-18 09:08**MOT test number** 651856916755**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush Front of joint (2.5.A.1c)**MOT #7** 2016-08-01 09:25**MOT test number** 664822352398**Result** ✓ Passed**MOT #6** 2015-08-28 14:26**MOT test number** 861108119090**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-08-22 09:56**MOT test number** 836014634265**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-08-30 09:10**MOT test number** 365122743443**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Items removed from driver's view prior to test**Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)



|                 |                  |
|-----------------|------------------|
| MOT #3          | 2012-08-28 16:09 |
| MOT test number | 628481842261     |
| Result          | ✓ Passed         |

|                         |                                                        |
|-------------------------|--------------------------------------------------------|
| MOT #2                  | 2012-08-28 16:09                                       |
| MOT test number         | 866651442233                                           |
| Result                  | ✗ Failed                                               |
| Pass with rectification | Offside Front position lamp(s) not working (1.1.A.3b)  |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) |
| Pass with rectification | Nearside Headlamp aim too low (1.8)                    |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2011-08-30 10:16 |
| MOT test number | 776712241201     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
1 December 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 June              |
| <b>Days left</b>        | 33                              |
| <b>MOT expiry date</b>  | 1 December 2024                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                                |            |
|------------------------------------------------|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | K          |
| <b>Single payment (12 months)</b>              | £ 395,00,- |
| <b>Single six month payment</b>                | £ 217,25,- |
| <b>Total payable by 12 monthly instalments</b> | £ 414,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |                                                                                                     |
|----------------------|-----------------------------------------------------------------------------------------------------|
| Number of plates     | 1                                                                                                   |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2024-03-29                                                                                          |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2024-03-29                                                                                          |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2008-09-01               |
| Last registration          | 2023-11-30               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2008-09-01 | 9 mi       |
| Registration #2  | 2011-08-30 | 55.230 mi  |
| Registration #3  | 2012-08-28 | 80.442 mi  |
| Registration #4  | 2013-08-30 | 95.080 mi  |
| Registration #5  | 2014-08-22 | 106.261 mi |
| Registration #6  | 2015-08-28 | 117.501 mi |
| Registration #7  | 2016-08-01 | 122.235 mi |
| Registration #8  | 2017-08-18 | 128.235 mi |
| Registration #9  | 2017-08-18 | 128.235 mi |
| Registration #10 | 2018-08-01 | 133.235 mi |
| Registration #11 | 2019-08-01 | 138.235 mi |
| Registration #12 | 2020-08-01 | 143.235 mi |
| Registration #13 | 2021-08-01 | 148.235 mi |
| Registration #14 | 2022-08-01 | 153.235 mi |
| Registration #15 | 2023-08-01 | 158.235 mi |
| Registration #16 | 2023-11-30 | 163.235 mi |
| Registration #17 | 2023-11-30 | 163.235 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1898 mm |
| Height              | 1743 mm |
| Length              | 4798 mm |
| Wheel base          | 2857 mm |
| Kerb weight         | 2148 kg |
| Max. allowed weight | 2750 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 68 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

|                 |        |
|-----------------|--------|
| Number of axles | 2      |
| Engine number   | 631863 |