



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Yellow
Year of manufacture	2006
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-11-04
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-20
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	20
Total items failed	12

MOT #20	2024-03-09 13:14
MOT test number	228342401323
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Exhaust flexi pipe worn
Advice	Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19	2023-03-21 11:40
MOT test number	738707103174
Result	✓ Passed

MOT #18	2022-02-04 13:50
MOT test number	825680634662
Result	✓ Passed

MOT #17	2020-09-01 14:32
MOT test number	163996901154
Result	✓ Passed

**MOT #16** 2020-08-28 15:54**MOT test number** 180009813925**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #15** 2019-06-26 09:44**MOT test number** 996088155685**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**MOT #14** 2018-07-12 12:36**MOT test number** 732195131974**Result** ✓ Passed**Advice** Nearside front suspension arm console bush split**MOT #13** 2018-07-11 13:55**MOT test number** 830457826696**Result** ✗ Failed**Advice** Offside front tyre outer sidewall scuffed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside front suspension arm console bush split**MOT #12** 2017-07-04 15:50**MOT test number** 971637101924**Result** ✓ Passed

**MOT #11** 2016-07-11 12:07**MOT test number** 600528965014**Result** ✓ Passed**Advice** Front brake discs corroded**Advice** Handbrake reserve travel low**MOT #10** 2015-07-13 16:56**MOT test number** 707144295102**Result** ✓ Passed**Notice** Nearside wiper smearing**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Notice** Offside w/washer poor**MOT #9** 2015-07-13 09:54**MOT test number** 546344395155**Result** ✗ Failed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Notice** Nearside wiper smearing**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Offside w/washer poor**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2014-07-11 15:05**MOT test number** 646352594114**Result** ✓ Passed**Notice** Mileometer inop**Advice** Offside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)

**MOT #7** 2013-07-08 10:46**MOT test number** 769299083197**Result** ✓ Passed**MOT #6** 2012-07-17 12:43**MOT test number** 848859292151**Result** ✓ Passed**MOT #5** 2011-07-11 15:33**MOT test number** 219622291477**Result** ✓ Passed**MOT #4** 2011-07-11 15:33**MOT test number** 857902791194**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Rear fog lamp not working (1.3.2b)
- Pass with rectification** All position lamps not working (1.1.A.3b)
- Pass with rectification** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**MOT #3** 2010-07-13 12:18**MOT test number** 793764690119**Result** ✓ Passed



MOT #2

2009-07-07 15:34

MOT test number

971458389165

Result

✓ Passed

Notice

Rear fog lamp intermitantly does not work. O.K. at time of test

MOT #1

2009-07-07 12:37

MOT test number

212058089102

Result

✗ Failed

Fail

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Notice

Rear fog lamp intermitantly does not work. O.K. at time of test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
20 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	20 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2006-07-20
Last registration	2024-03-09
Complete history	<a href="#">See info</a>



Registration #1	2006-07-20	27 mi
Registration #2	2009-07-07	3.200 mi
Registration #3	2009-07-07	3.200 mi
Registration #4	2010-07-13	3.357 mi
Registration #5	2011-07-11	3.856 mi
Registration #6	2013-07-08	4.212 mi
Registration #7	2015-07-13	45.114 mi
Registration #8	2016-07-07	55.377 mi
Registration #9	2017-07-07	55.377 mi
Registration #10	2018-07-07	55.377 mi
Registration #11	2019-07-07	55.377 mi
Registration #12	2020-07-07	55.377 mi
Registration #13	2021-07-07	55.377 mi
Registration #14	2022-07-07	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 255340