



RENAULT

**BG06VOA**

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-14
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #21** 2022-11-01 12:56**MOT test number** 149299087812**Result** ✓ Passed**Next expiry date** 2023-10-31**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #20** 2022-10-24 16:23**MOT test number** 855393093632**Result** ✗ Failed**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #19** 2021-09-20 15:18**MOT test number** 789998526438**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing all tyres ageing cracks (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**MOT #18**

2021-09-20 15:18

**MOT test number**

183211863058

**Result****✗ Failed****Pass with rectification**

Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice**

Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**Advice**

Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Tyre slightly damaged/cracking or perishing all tyres ageing cracks (5.2.3 (d) (ii))

**MOT #17**

2020-09-14 14:38

**MOT test number**

632241221209

**Result****✓ Passed****Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Handbrake just met requirements 16%

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2020-09-14 10:24

**MOT test number**

629710626201

**Result****✗ Failed****Pass with rectification**

Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice**

Handbrake just met requirements 16%

**Pass with rectification**

Offside Headlamp aim too high (4.1.2 (a))

**Fail**

Front Registration plate inscription illegible (0.1 (b))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Pass with rectification**

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Pass with rectification**

Nearside Headlamp aim too high (4.1.2 (a))

**Pass with rectification**

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail**

Front Registration plate inscription illegible (0.1 (b))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #15**

2019-09-09 13:14

**MOT test number**

139817134678

**Result****✓ Passed****Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2019-09-06 10:04

**MOT test number**

870964850405

**Result****✗ Failed**

- Fail** Nearside Front Brake hose excessively chafed (1.1.12 (b) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2018-10-05 14:30

**MOT test number**

936982128536

**Result****✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2018-10-05 09:55**MOT test number** 518974310853**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2017-10-03 14:00**MOT test number** 698729750669**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2016-10-07 10:18**MOT test number** 454253680863**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear cracks on tyre**Advice** Oil leak**MOT #9** 2016-10-06 11:54**MOT test number** 708512482526**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Oil leak**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear cracks on tyre

**MOT #8** 2016-10-05 10:44**MOT test number** 283837710258**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2015-06-30 17:37**MOT test number** 206181085483**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Lower Ball joint has slight play (2.2.B.1f)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-07-08 16:01**MOT test number** 747169284172**Result** ✓ Passed**MOT #5** 2013-07-05 10:53**MOT test number** 765366783171**Result** ✓ Passed



MOT #4	2012-06-27 10:09
MOT test number	948739972103
Result	✓ Passed
MOT #3	2011-06-28 12:06
MOT test number	897969271145
Result	✓ Passed
MOT #2	2010-06-22 15:41
MOT test number	560943170177
Result	✓ Passed
<div>AdviceTyre worn close to the legal limit (4.1.E.1)</div>	
MOT #1	2009-07-06 11:59
MOT test number	724567289161
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-16
Last registration	2022-11-01
Complete history	<a href="#">See info</a>



Registration #1	2006-06-16	26 mi
Registration #2	2009-07-06	22.824 mi
Registration #3	2010-06-22	27.949 mi
Registration #4	2011-06-28	34.022 mi
Registration #5	2012-06-27	39.155 mi
Registration #6	2013-07-05	44.284 mi
Registration #7	2014-07-08	49.529 mi
Registration #8	2015-06-30	56.610 mi
Registration #9	2016-10-05	65.019 mi
Registration #10	2016-10-06	65.027 mi
Registration #11	2016-10-07	65.027 mi
Registration #12	2016-10-07	65.027 mi
Registration #13	2016-10-07	65.027 mi
Registration #14	2016-10-07	65.027 mi
Registration #15	2016-10-07	65.027 mi
Registration #16	2016-10-07	65.027 mi
Registration #17	2016-10-07	65.027 mi
Registration #18	2016-10-07	65.027 mi
Registration #19	2016-10-07	65.027 mi
Registration #20	2016-10-07	65.027 mi
Registration #21	2016-10-07	65.027 mi
Registration #22	2016-10-07	65.027 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D089414