





report date: 2024-03-29

#### General information

| Make                | MINI           |
|---------------------|----------------|
| Model               | MINI COOPER SD |
| Colour              | Red            |
| Year of manufacture | 2013           |
| Top speed           | 123 mph        |
| 0 - 60 mph          | 9.3 seconds    |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 141 BHP             |
|-------------------------|---------------------|
| Max. torque             | 305 Nm at 1.750 rpm |
| Engine capacity         | 1.995 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 54.3 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 61.4 mpg            |
| CO2 emission            | 122 g/km            |
| CO2 label               | D                   |



CarCheck.co.uk page 1/12



## Internet history

#### Entry 4

Date 2023-12-09

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 3

| Date          | 2022-11-14         |
|---------------|--------------------|
| Pictures      | 0                  |
| Listing price | <u>View report</u> |

#### source: carcraft.co.uk


#### Entry 2

Date 2022-11-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

| Date          | 2021-06-23  |
|---------------|-------------|
| Pictures      | 1           |
| Listing price | View report |

CarCheck.co.uk page 2/12



source: autotrader.co.uk



MOT history

| MOT expiry date    | 2025-01-01 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 2          |
| Total advice items | 9          |
| Total items failed | 4          |

| MOT #10          | 2024-01-02 15:45 |
|------------------|------------------|
| MOT test number  | 810580243483     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-01       |

| MOT #9          | 2022-11-10 14:59 |
|-----------------|------------------|
| MOT test number | 487476925329     |
| Result          | <b>√</b> Passed  |

| MOT #8          | 2021-11-22 15:48 |
|-----------------|------------------|
| MOT test number | 499495010182     |
| Result          | <b>✓</b> Passed  |

| MOT #7 | 2021-11-19 15:18 |
|--------|------------------|

**MOT test number** 911538694938

Result

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

X Failed

Fail Windscreen damaged and affecting the driver's view of the road cracked (3.2 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 3/12



| MOT #6   |  | 2021-06-11 00:47 |
|----------|--|------------------|
| MOT test | number   | 548453310245     |
| Result   |  | ✓ Passed         |
|          |  |                  |
| MOT #5   |  | 2020-08-13 08:28 |
| MOT test | number   | 199448415674     |
| Result   |  | ✓ Passed         |
|          |  |                  |
| MOT #4   |  | 2017-09-20 13:35 |
| MOT test | number   | 745412924501     |
| Result   |  | ✓ Passed         |
|          |  |                  |
| MOT #3   |  | 2017-02-06 14:58 |
| MOT test | number   | 127264127615     |
| Result   |  | ✓ Passed         |
| Advice   | Front Brake pad(s) wearing thin (3.5.1g)                     |                  |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1)   |                  |
| Advice   | Child Seat fitted not allowing full inspection of adult belt |                  |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1)  |                  |

CarCheck.co.uk page 4/12



MOT #2 2017-02-06 14:58

**MOT test number** 695790212870

**Result** ★ Failed

Advice Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Rear registration plate dirty (6.3.1d)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Front registration plate dirty (6.3.1d)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-01-27 16:13

**MOT test number** 458372892994

CarCheck.co.uk page 5/12



# Tax & MOT check



| Tax status       | Valid until 1 January |
|------------------|-----------------------|
| Days left        | 247                   |
| MOT expiry date  | 1 January 2025        |
| Full MOT history | See MOT history       |

#### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners did check it in the premium report and see all owner registrations. Download the full report  |             |
|--|-------------|
|  |             |
| HARMAN CO.   |             |
| ***************************************  |             |
| THE STATE OF THE S |             |
|  |             |
| HEREERS  |             |
| ***************************************  |             |
| *************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this MINI had different number plates.  |             |
| Number of plates   |             |
| Current registration   | OK SIE      |
| Plate since  |             |
| Current registration   | NK SIN      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2013-09-26 |
| Last registration          | 2024-01-02 |
| Complete history           | See info   |



| Registration #1  | 2013-09-26 | 24 mi      |
|------------------|------------|------------|
| Registration #2  | 2016-01-27 | 26.717 mi  |
| Registration #3  | 2017-02-06 | 45.089 mi  |
| Registration #4  | 2017-02-06 | 45.089 mi  |
| Registration #5  | 2017-09-20 | 50.577 mi  |
| Registration #6  | 2020-08-13 | 68.387 mi  |
| Registration #7  | 2021-06-11 | 81.221 mi  |
| Registration #8  |            | 11.777 es  |
| Registration #9  |            | 11.777 es  |
| Registration #10 |            | 11.777 es  |
| Registration #11 |            | 91.777 esi |
| Registration #12 |            | 11.777 es  |
| Registration #13 |            | 91.777 esi |
| Registration #14 |            | 11.777 es  |
| Registration #15 |            | 11.777 es  |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 84%             |
| Children       | 83%             |
| Pedestrian     | 63%             |
| Safety systems | 71%             |
| Overall rating | 78%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1789 mm |
|---------------------|---------|
| Height              | 1561 mm |
| Length              | 4110 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1320 kg |
| Max. allowed weight | 1830 kg |

# Additional information

| Fuel tank capacity                | 47               |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 12        |

Number of axles 2

Engine number 73108603