



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 SE AWD
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-05-02
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #10	2023-05-02 16:44
MOT test number	628170449405
Result	✓ Passed
Next expiry date	2024-05-02
Advice	Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Items removed from driver's view prior to test

MOT #9	2023-05-02 08:42
MOT test number	994539517378
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Advice	Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #8	2022-05-03 17:05
MOT test number	951593264334
Result	✓ Passed

**MOT #7** 2022-05-03 10:02**MOT test number** 563271596790**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Minor** Offside Rear Anti-roll bar ball joint dust cover severely deteriorated drop link (5.3.4 (b) (i))**Fail** Offside Front Windscreen washer provides insufficient washer liquid jet (3.5 (a))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Minor** Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated drop link (5.3.4 (b) (i))**MOT #6** 2021-04-29 12:50**MOT test number** 180512583683**Result** ✓ Passed**MOT #5** 2020-01-06 14:28**MOT test number** 904841663294**Result** ✓ Passed**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**MOT #4** 2019-01-09 15:31**MOT test number** 191546228822**Result** ✓ Passed**MOT #3** 2018-01-08 14:59**MOT test number** 299203244247**Result** ✓ Passed



MOT #2	2017-01-12 16:47
MOT test number	163252723124
Result	✓ Passed

MOT #1	2016-01-21 10:26
MOT test number	177689123990
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 May 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	2 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-23
Last registration	2023-05-02
Complete history	See info



Registration #1	2013-01-23	9 mi
Registration #2	2016-01-21	21.425 mi
Registration #3	2017-01-12	25.551 mi
Registration #4	2018-01-08	28.473 mi
Registration #5	2019-01-09	30.740 mi
Registration #6	2020-01-06	32.922 mi
Registration #7	2020-05-20	35.277 mi
Registration #8	2020-05-20	35.277 mi
Registration #9	2020-05-20	35.277 mi
Registration #10	2020-05-20	35.277 mi
Registration #11	2020-05-20	35.277 mi
Registration #12	2020-05-20	35.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1851 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1277808