





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	140 CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



# Internet history

## Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2024-11-10
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #7		2023-10-24 11:22
MOT test	number	266235439297
Result		✓ Passed
Next expi	ry date	2024-11-10
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.3mm (5.2.3 (e))	

MOT #6		2022-11-03 11:43
MOT test i	number	944394788349
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on both	edges (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge getting low on 1.	87 mm (5.2.3 (e))
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on both edges (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge getting low on 2.43	l mm (5.2.3 (e))

MOT #5	2021-10-28 10:38
MOT test	number 877131960161
Result	✓ Passed
Advice edges (5.2	Offside Rear Tyre worn close to legal limit/worn on edge getting low on 2.47 mm/wearing on both (2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge getting low on 2.49 mm (5.2.3 (e))

CarCheck.co.uk page 3/11



Result

RJ64RNO report date: 2024-03-29

✓ Passed

 MOT #4
 2020-11-11 15:43

 MOT test number
 364627427029

 Result
 ✓ Passed

 MOT #3
 2020-01-24 12:00

 MOT test number
 202775327245

Advice Front Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))

MOT #2

MOT test number

626823411335

Result

Advice Tyre worn close to legal limit/worn on edge both rear 205/60/16v (5.2.3 (e))

MOT #1	2018-01-19 10:01
MOT test number	706382361501
Result	✓ Passed

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	10 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.		NDAI
********		
***************************************		
	More info	>
Plate changes  See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-12-30
Last registration	2023-10-24
Complete history	See info



Registration #1	2014-12-30	8 mi
Registration #2	2018-01-19	24.659 mi
Registration #3	2019-01-09	33.222 mi
Registration #4	2020-01-24	43.520 mi
Registration #5	2020-11-11	45.912 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

**Engine number** 

D4FDEU428157