



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-22
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-09-20
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-27
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	19
Total items failed	10

MOT #20	2023-07-31 11:20
MOT test number	113041952987
Result	✓ Passed
Next expiry date	2024-08-27
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2023-07-31 08:23
MOT test number	159760445023
Result	✗ Failed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #18** 2022-08-19 15:22**MOT test number** 471450272004**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Service brake grabbing slightly (1.2.1 (c))**MOT #17** 2022-08-17 09:52**MOT test number** 499507615851**Result** ✗ Failed**Advice** Offside Rear Service brake grabbing slightly (1.2.1 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Headlamp insecure (4.1.1 (c))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #16** 2021-08-24 07:11**MOT test number** 329832253834**Result** ✓ Passed**MOT #15** 2020-08-19 07:28**MOT test number** 249868341584**Result** ✓ Passed

**MOT #14** 2019-08-27 07:35**MOT test number** 475938035659**Result** Passed**MOT #13** 2019-08-27 07:35**MOT test number** 736026616302**Result** Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2018-08-28 08:52**MOT test number** 563824601083**Result** Passed**MOT #11** 2018-08-28 08:52**MOT test number** 612391647797**Result** Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #10** 2016-12-02 11:43**MOT test number** 414636141925**Result** Passed**MOT #9** 2015-12-01 10:29**MOT test number** 176375484564**Result** Passed

**MOT #8** 2014-12-01 11:34**MOT test number** 517165334342**Result** ✓ Passed**MOT #7** 2013-12-02 09:29**MOT test number** 296096433372**Result** ✓ Passed**MOT #6** 2012-11-16 11:01**MOT test number** 486271922393**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2011-11-08 17:51**MOT test number** 548342111302**Result** ✓ Passed

- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2010-11-24 15:53**MOT test number** 303638820393**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2009-11-26 14:32
MOT test number	411200239309
Result	✓ Passed
MOT #2	2008-11-25 17:43
MOT test number	771960238362
Result	✓ Passed
MOT #1	2007-11-13 13:08
MOT test number	163797617375
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
27 August 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-12-02
Last registration	2023-07-31
Complete history	See info



Registration #1	2004-12-02	13 mi
Registration #2	2007-11-13	11.836 mi
Registration #3	2008-11-25	19.372 mi
Registration #4	2009-11-26	25.785 mi
Registration #5	2010-11-24	32.025 mi
Registration #6	2011-11-08	37.906 mi
Registration #7	2012-11-16	43.379 mi
Registration #8	2013-12-02	49.275 mi
Registration #9	2014-12-01	57.037 mi
Registration #10	2015-12-01	57.912 mi
Registration #11	2016-12-02	61.000 mi
Registration #12	2018-08-28	68.668 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi
Registration #20	2019-05-29	75.377 mi
Registration #21	2019-05-29	75.377 mi
Registration #22	2019-05-29	75.377 mi
Registration #23	2019-05-29	75.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4ZZ1994481