



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO TREKKA DCI 80
Colour	Grey
Year of manufacture	2004
Top speed	88 mph
0 - 60 mph	16.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	179 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	196 g/km
CO2 label	J







Internet history

Entry 1

Date	2022-02-19
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-05-16
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	102
Total items failed	38

MOT #22	2024-04-22 12:52
MOT test number	687355493310
Result	✓ Passed
Next expiry date	2025-05-16
Minor	Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))



MOT #21

2023-05-17 13:23

MOT test number

981845453205

Result

✓ Passed

- Minor

Central Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Play in steering rack inner joint(s)
- Advice

Rear fuel tank strap/ holder corroded
- Advice

Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor

Offside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Rear Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))
- Advice

Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Front Brake hose slightly deteriorated (1.1.12 (b) (ii))



MOT #20

2023-05-05 12:58

MOT test number

151246630424

Result

✗ Failed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Headlamp aim too high (4.1.2 (a))

Fail

Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail

Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail

Nearside Undertray likely to become detached fuel tank (6.2.1 (a) (ii))

Minor

Offside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail

Nearside Front Seat belt not functioning as intended (7.1.2 (c))

Fail

Offside Rear Brake hose excessively deteriorated fouling (1.1.12 (b) (ii))

Fail

Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

Fail

Offside Front Windscreen in such a condition that visibility through swept area is seriously affected (3.2 (c) (ii))

Minor

Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Central Rear Seat belt not functioning as intended (7.1.2 (c))

Advice

O/s and n/s front cv joints knocking

Fail

Offside Front Brake hose excessively deteriorated fouling clips missing (1.1.12 (b) (ii))

Advice

Rear Towball/hitch not fitted at time of test

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Headlamp aim too high (4.1.2 (a))

Fail

Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))

Fail

Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail

Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Undertray likely to become detached fuel tank (6.2.1 (a) (ii))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Rear Seat belt not functioning as intended (7.1.2 (c))

Advice Tow bar corroded

Fail Nearside Front Brake hose excessively deteriorated fouling clips missing (1.1.12 (b) (ii))

**MOT #19**

2023-04-24 15:55

MOT test number

635740616219

Result

✓ Passed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Nearside Front Inner Steering rack cv gaiter Deteriorated

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front top mount has play

Advice

Front Play in steering rack inner joint(s) nearside and offside

MOT #18

2023-04-24 15:55

MOT test number

880203926983

Result

✗ Failed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Nearside Front Inner Steering rack cv gaiter Deteriorated

Advice

Front Play in steering rack inner joint(s) nearside and offside

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Offside Front top mount has play

**MOT #17**

2022-04-26 11:49

MOT test number

980433281660

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Front Play in steering rack inner joint(s) both sides
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16

2021-04-27 15:19

MOT test number

174853829250

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))
- Advice** Brake hose has slight corrosion to ferrule various (1.1.12 (f) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)

**MOT #15**

2021-04-01 13:20

MOT test number

525311817865

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn out of shape 1.6mm (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear exhaust joint poor.exhaust corroding.various underbody corrosion.various components corroding.
- Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** N/s/r wheel arch corroded.
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Rear Tyre fouling a part of the vehicle (5.2.3 (f))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing out of shape. (5.2.3 (e))
- Advice** Brake hose has slight corrosion to ferrule various (1.1.12 (f) (i))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Both rear flexi brake hoses poorly supported.
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

**MOT #14**

2020-01-22 10:18

MOT test number

691862200046

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Play in steering rack inner joint(s)**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #13**

2019-02-08 16:32

MOT test number

654229791276

Result

✓ Passed

Advice Slight play in nearside steering rack**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12**

2019-02-06 14:55

MOT test number

544914807147

Result

✗ Failed

Fail Central Prop shaft bearing excessively worn center prop shaft bearing (6.1.7 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Headlamps matched pair incorrect colour (4.1.4 (a))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



MOT #11	2017-03-15 14:40
MOT test number	539208625879
Result	✓ Passed
Advice	Rear brake pads on limit
Advice	Oil leak
Advice	Offside cv gaitor requires further securing soon
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Both rear chassis rails slightly corroded
Advice	Nearside steering rack joint has slight play
Advice	Front brake pads on limit
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Both front tyres wearing on inner edges
Advice	Offside track rod end has slight play

MOT #10	2016-02-13 12:37
MOT test number	801831873997
Result	✓ Passed
Advice	Both cv joints slightly worn
Advice	Both rear suspension arms slightly corroded
Advice	Nearside steering rack gaiter perished

**MOT #9** 2014-12-09 17:17**MOT test number** 149373844348**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2013-12-13 10:34**MOT test number** 596947543385**Result** ✓ Passed

- Notice** Handbrake travel high
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)
- Notice** Offside washer jet poor
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Play in steering rack inner joint(s)
- Advice** Offside Rear Brake pipe slightly damaged (2.2.D.2b)

MOT #7 2012-10-19 16:03**MOT test number** 299703892285**Result** ✓ Passed**MOT #6** 2011-10-19 12:44**MOT test number** 935632391290**Result** ✓ Passed

- Notice** Slight play in nearside steering rack
- Notice** Handbrake travel high

**MOT #5** 2009-08-07 11:51**MOT test number** 922389219292**Result** ✓ Passed**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Rear brake disc slightly pitted (3.5.1h)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** N/s/r tyre cut in side wall but not exposing cords**MOT #4** 2009-08-04 10:00**MOT test number** 524926419259**Result** ✗ Failed**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Notice** N/s/r tyre cut in side wall but not exposing cords**Advice** Rear brake disc slightly pitted (3.5.1h)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #3** 2008-08-15 16:49**MOT test number** 701428828206**Result** ✓ Passed**MOT #2** 2008-08-14 17:12**MOT test number** 962187128248**Result** ✗ Failed**Fail** Rear Shock absorber has an excessively worn bush (2.7.4)**Pass with rectification** Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Fail** Parking brake lever has no reserve travel (3.1.6b)



MOT #1	2007-08-28 16:33
MOT test number	302530647273
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 May 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	16 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-04-06
Last registration	2024-04-22
Complete history	See info



Registration #1	2004-04-06	7 mi
Registration #2	2007-08-28	53.231 mi
Registration #3	2008-08-14	64.181 mi
Registration #4	2008-08-15	64.181 mi
Registration #5	2009-08-04	76.043 mi
Registration #6	2009-08-07	76.043 mi
Registration #7	2011-10-19	96.443 mi
Registration #8	2012-10-19	104.621 mi
Registration #9	2013-12-13	108.524 mi
Registration #10	2014-12-09	113.314 mi
Registration #11	2016-02-13	121.001 mi
Registration #12	2017-03-15	128.407 mi
Registration #13	2018-04-20	135.277 mi
Registration #14	2019-05-20	142.147 mi
Registration #15	2020-06-20	149.017 mi
Registration #16	2021-07-20	155.887 mi
Registration #17	2022-08-20	162.757 mi
Registration #18	2023-09-20	169.627 mi
Registration #19	2024-10-20	176.497 mi
Registration #20	2025-11-20	183.367 mi
Registration #21	2026-12-20	190.237 mi
Registration #22	2027-01-20	197.107 mi
Registration #23	2028-02-20	203.977 mi
Registration #24	2029-03-20	210.847 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1900 mm
Length	4035 mm
Wheel base	2624 mm
Kerb weight	1330 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	C020170