




report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-12-22
Pictures	36
Listing price	View report




source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-09
Pictures	12
Listing price	View report





Video viewing
Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)

source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-24
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	17
Total items failed	6

MOT #12 2023-10-14 10:58

MOT test number 877876639823

Result ✓ Passed

Next expiry date 2024-10-24

Advice Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11 2022-10-14 09:48

MOT test number 723729382867

Result ✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Front tyres wearing on inner edge slightly

Advice N/s rear tyre worn on inner edge

MOT #10 2021-10-25 10:59

MOT test number 722673601398

Result ✓ Passed

**MOT #9** 2020-07-17 08:46**MOT test number** 127177184619**Result** ✓ Passed**MOT #8** 2020-07-17 08:46**MOT test number** 434085647393**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7** 2019-06-28 09:49**MOT test number** 437830216404**Result** ✓ Passed**MOT #6** 2018-07-03 16:09**MOT test number** 242888257226**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both low (5.2.3 (e))**MOT #5** 2018-07-03 08:43**MOT test number** 829779309211**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Suspension arm pin or bush excessively worn wishbone bushs rear bushs (5.3.4 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both low (5.2.3 (e))

**MOT #4** 2017-07-04 13:52**MOT test number** 446941096151**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-07-26 12:04**MOT test number** 991897546820**Result** ✓ Passed**MOT #2** 2016-07-25 14:03**MOT test number** 367001224487**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2015-05-20 17:22**MOT test number** 977260745119**Result** ✓ Passed**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Outer Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY12NWX
Plate since	2024-03-29
Current registration	YY12NWX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-24
Last registration	2023-10-14
Complete history	See info



Registration #1	2012-07-24	20 mi
Registration #2	2015-05-20	18.574 mi
Registration #3	2016-07-25	23.202 mi
Registration #4	2016-07-26	23.204 mi
Registration #5	2017-07-04	31.290 mi
Registration #6	2018-07-03	39.540 mi
Registration #7	2018-07-03	39.540 mi
Registration #8	2019-06-28	46.617 mi
Registration #9	2019-06-28	46.617 mi
Registration #10	2019-06-28	46.617 mi
Registration #11	2019-06-28	46.617 mi
Registration #12	2019-06-28	46.617 mi
Registration #13	2019-06-28	46.617 mi
Registration #14	2019-06-28	46.617 mi
Registration #15	2019-06-28	46.617 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033