



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S TDI (70BHP)
Colour	Silver
Year of manufacture	2007
Top speed	102 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	155 Nm at 1.600 rpm
Engine capacity	1.400 cc
Cylinders	3
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2021-12-05
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	21
Total items failed	20

MOT #17 2020-12-05 11:21

MOT test number 749019308131

Result ✓ Passed

Next expiry date 2021-12-05

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Minor Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Arch Damaged N/S/R but not Sharp

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2020-12-05 11:21

MOT test number

429991900700

Result**✗ Failed**

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Arch Damaged N/S/R but not Sharp

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #15

2019-05-29 09:08

MOT test number

500366167572

Result**✓ Passed****MOT #14**

2018-06-01 15:43

MOT test number

883203065366

Result**✓ Passed**

**MOT #13**

2018-05-31 06:39

MOT test number

692140398628

Result**✗ Failed****Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Hydraulic brake cylinder leaking and braking performance affected (1.1.16 (b) (ii))**Fail** Central Rear Seat belt damaged protective cover missing may lead becoming unbuckled (7.1.2 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Steering system does not appear to go from lock to lock fully**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Seat belt retracting mechanism defective (7.1.2 (e))**MOT #12**

2017-06-06 11:35

MOT test number

410445790019

Result**✓ Passed****MOT #11**

2017-06-05 13:50

MOT test number

202647618389

Result**✗ Failed****Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #10**

2016-06-03 09:03

MOT test number

199704352781

Result**✓ Passed**

**MOT #9** 2016-06-03 08:08**MOT test number** 503706192744**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2015-06-04 17:05**MOT test number** 988825555146**Result** ✓ Passed**MOT #7** 2015-06-03 12:30**MOT test number** 636184255161**Result** ✗ Failed**Fail** Nearside front brake excessively fluctuating (3.7.B.3)**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**Fail** Offside front brake excessively fluctuating (3.7.B.3)**MOT #6** 2014-08-22 12:25**MOT test number** 138704734261**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-08-21 15:14**MOT test number** 118333734265**Result** ✗ Failed

- Fail** Front Drag link end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2013-08-22 11:36**MOT test number** 745824033240**Result** ✓ Passed

- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-07-26 16:34**MOT test number** 399668602232**Result** ✓ Passed**MOT #2** 2011-09-13 11:47**MOT test number** 667366951263**Result** ✓ Passed**MOT #1** 2010-09-09 12:10**MOT test number** 600472250293**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
18 December 2020

✕
MOT

Expired:
5 December 2021

Tax status	Expired at 18 December 2020
Days left	1227 days too late
MOT expiry date	5 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VO57WWT
Plate since	2019-06-29
Current registration	 VO57WWT
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-18
Last registration	2020-12-05
Complete history	See info



Registration #1	2007-09-18	25 mi
Registration #2	2010-09-09	45.778 mi
Registration #3	2011-09-13	58.302 mi
Registration #4	2012-07-26	68.002 mi
Registration #5	2013-08-22	77.038 mi
Registration #6	2014-08-21	86.497 mi
Registration #7	2014-08-22	86.498 mi
Registration #8	2015-06-03	93.324 mi
Registration #9	2015-06-04	93.324 mi
Registration #10	2016-06-03	93.324 mi
Registration #11	2016-06-04	93.324 mi
Registration #12	2016-06-05	93.324 mi
Registration #13	2016-06-06	93.324 mi
Registration #14	2016-06-07	93.324 mi
Registration #15	2016-06-08	93.324 mi
Registration #16	2016-06-09	93.324 mi
Registration #17	2016-06-10	93.324 mi
Registration #18	2020-12-05	93.324 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1267 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BNM197184