




report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI SPORT
Colour	Red
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M





Internet history

Entry 1

Date	2022-07-26
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-02-09
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	69
Total items failed	8

MOT #19	2023-02-03 11:03
MOT test number	984064263015
Result	✓ Passed
Next expiry date	2024-02-09

MOT #18	2023-02-03 10:32
MOT test number	630255553714
Result	✗ Failed
MAJOR	Nearside Front Headlamp aim too low (4.1.2 (a))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #17	2022-01-17 14:29
MOT test number	874626997763
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both sides towards inside close to limit and inner edges 0mm (5.2.3 (e))
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive rear subframe o/s/f mount area on chassis and crossmember (5.3.6 (a) (i))

**MOT #16**

2022-01-10 11:02

MOT test number

449000086032

Result**✗ Failed**

Advice Rear Subframe mounting prescribed area is corroded but not considered excessive rear subframe o/s/f mount area on chassis and crossmember (5.3.6 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge both sides towards inside close to limit and inner edges 0mm (5.2.3 (e))

MAJOR Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MAJOR Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #15

2021-01-21 14:03

MOT test number

478523936126

Result**✓ Passed**

Advice Chassis corroded

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Play in steering rack inner joint(s)

MOT #14

2021-01-14 08:40

MOT test number

277780380279

Result**✗ Failed**

Advice Play in steering rack inner joint(s)

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Chassis corroded

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #13**

2020-01-20 11:25

MOT test number

720998559912

Result

✓ Passed

- Advice** Front Both tyres wearing on edge
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Wheel bearing has slight play Both (5.1.3 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Chassis corroded
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12

2020-01-10 14:30

MOT test number

459317622007

Result

✗ Failed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Play in steering rack inner joint(s)
- MAJOR** Nearside Rear Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Chassis corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Wheel bearing has slight play Both (5.1.3 (a) (i))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Rear Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Both tyres wearing on edge

**MOT #11**

2019-01-17 09:52

MOT test number

991138040535

Result

✓ Passed

Advice Play in steering rack inner joint(s)**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Leaking grease (6.1.7 (g) (i))**Advice** Chassis corroded**MOT #10**

2019-01-10 09:58

MOT test number

197558447194

Result

✗ Failed

Advice Play in steering rack inner joint(s)**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Leaking grease (6.1.7 (g) (i))**Advice** Chassis corroded**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9**

2018-01-23 08:24

MOT test number

786661127059

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Central Stop lamp obscured but not more than 50% (1.2.1c)**Advice** Offside Front Tyre worn close to the legal limit 2.3mm (4.1.E.1)**Advice** Rear both tyres wearing on inner edge and perishing**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear Tyre worn close to the legal limit 2.6mm (4.1.E.1)

**MOT #8** 2018-01-12 13:28**MOT test number** 999214439262**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 2.6mm (4.1.E.1)**Advice** Centre stop lamp disconnected**Fail** Exhaust has a major leak of exhaust gases centre box (7.1.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear both tyres wearing on inner edge and perishing**Fail** Windscreen washer provides insufficient washer liquid both (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit 2.3mm (4.1.E.1)**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**MOT #7** 2017-02-01 10:59**MOT test number** 390761963499**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #6** 2016-02-10 09:55**MOT test number** 415700271364**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**MOT #5** 2015-03-11 14:10**MOT test number** 389500375035**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2015-02-18 16:41**MOT test number** 895219745042**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Front Steering column shaft has excessive end float (2.1.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Front front brake application uneven (3.7.B.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2014-03-03 12:20**MOT test number** 168382164025**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)



MOT #2	2014-03-01 11:24
MOT test number	446150864048
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #1	2012-08-27 11:35
MOT test number	908060342211
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-25
Last registration	2023-02-03
Complete history	See info



Registration #1	2009-09-25	13 mi
Registration #2	2012-08-27	40.212 mi
Registration #3	2014-03-01	54.447 mi
Registration #4	2014-03-03	54.447 mi
Registration #5	2015-02-18	66.070 mi
Registration #6	2015-03-11	66.412 mi
Registration #7	2016-02-10	74.136 mi
Registration #8	2017-02-01	78.473 mi
Registration #9	2018-01-12	82.916 mi
Registration #10	2018-01-23	83.000 mi
Registration #11	2019-01-10	88.274 mi
Registration #12	2019-01-20	91.337 mi
Registration #13	2019-01-20	91.337 mi
Registration #14	2019-01-20	91.337 mi
Registration #15	2019-01-20	91.337 mi
Registration #16	2019-01-20	91.337 mi
Registration #17	2019-01-20	91.337 mi
Registration #18	2019-01-20	91.337 mi
Registration #19	2019-01-20	91.337 mi
Registration #20	2019-01-20	91.337 mi
Registration #21	2019-01-20	91.337 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Max. allowed weight	2880 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	602422