



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | PIXO N-TEC |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 96 mph |
| 0 - 60 mph | 14.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 67 BHP |
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 103 g/km |
| CO2 label | B |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 9 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-20 |
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 10 |
| Total items failed | 12 |

| | |
|------------------|--|
| MOT #14 | 2023-09-21 14:35 |
| MOT test number | 329399741494 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-20 |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material x 2 (1.1.11 (c)) |
| Advice | Offside Rear Outer Nail in tyre |

| | |
|-----------------|------------------|
| MOT #13 | 2022-09-09 12:38 |
| MOT test number | 470997021625 |
| Result | ✓ Passed |

| | |
|-------------------------|---|
| MOT #12 | 2022-09-08 12:37 |
| MOT test number | 212103775888 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Nearside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure tyre wall (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #11 | 2021-08-13 08:08 |
| MOT test number | 524127784530 |
| Result | ✓ Passed |

**MOT #10**

2020-04-14 12:39

MOT test number

246425597169

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement split (5.3.4 (a) (i))**MOT #9**

2020-04-02 13:48

MOT test number

249734591211

Result

✗ Failed

Fail Horn not working (7.7 (a) (ii))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement split (5.3.4 (a) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**MOT #8**

2018-03-22 09:43

MOT test number

962527909586

Result

✓ Passed

MOT #7

2018-03-21 14:35

MOT test number

970536563907

Result

✗ Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Central Front Horn not working (1.6.2a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Central Front Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #6** 2017-03-30 11:50**MOT test number** 232234100896**Result** ✓ Passed**MOT #5** 2016-03-31 15:32**MOT test number** 377623616322**Result** ✓ Passed**MOT #4** 2016-03-31 14:10**MOT test number** 975774035069**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2015-04-01 10:11**MOT test number** 258141295045**Result** ✓ Passed**MOT #2** 2014-04-09 14:12**MOT test number** 198829494073**Result** ✓ Passed**Notice** All tyres perished and cracked**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-03-28 14:26**MOT test number** 166397483467**Result** ✓ Passed**Notice** All four tyres cracking



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 20 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2010-03-31 |
| Last registration | 2023-09-21 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-03-31 | 6 mi |
| Registration #2 | 2013-03-28 | 8.735 mi |
| Registration #3 | 2014-04-09 | 10.664 mi |
| Registration #4 | 2015-04-01 | 12.652 mi |
| Registration #5 | 2016-03-31 | 14.581 mi |
| Registration #6 | 2016-03-31 | 14.581 mi |
| Registration #7 | 2017-03-30 | 16.128 mi |
| Registration #8 | 2018-03-21 | 16.708 mi |
| Registration #9 | 2019-03-20 | 16.708 mi |
| Registration #10 | 2019-03-20 | 16.708 mi |
| Registration #11 | 2019-03-20 | 16.708 mi |
| Registration #12 | 2019-03-20 | 16.708 mi |
| Registration #13 | 2019-03-20 | 16.708 mi |
| Registration #14 | 2019-03-20 | 16.708 mi |
| Registration #15 | 2019-03-20 | 16.708 mi |
| Registration #16 | 2019-03-20 | 16.708 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1630 mm |
| Height | 1470 mm |
| Length | 3565 mm |
| Wheel base | 2360 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1250 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 112085 |