





report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE V50
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2022-08-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #16 2022-08-02 08:38

MOT test number 509045065558

Result ✓ Passed

Next expiry date 2023-08-01

MOT #15 2022-07-29 15:29

MOT test number 188675445514

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Gearbox mounting defective Torque Reaction Mount.

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14 2021-10-22 15:11

MOT test number 847534747649

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2020-09-30 13:19

MOT test number 430754421978

Result ✓ Passed

MOT #12 2019-04-05 14:18

MOT test number 410718553600

Result ✓ Passed

MOT #11 2018-04-06 10:22

MOT test number 720131923927

CarCheck.co.uk page 3/12



MOT #10 2017-04-07 10:44

MOT test number 316677086622

Result ✓ Passed

Advice Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside rear brake fluctuating, but not excessively (3.7.B.3)

Advice Advise both front suspension arm bushes splitting

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #9 2017-03-29 11:21

MOT test number 835266762289

Result × Failed

Advice Offside rear brake fluctuating, but not excessively (3.7.B.3)

Advice Advise both front suspension arm bushes splitting

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Nearside Headlamp aim too low (1.8)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Advice Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint very slight (2.4.G.2)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Offside Headlamp aim too low (1.8)

Fail Front Exhaust system not adequately supported (7.1.1)

CarCheck.co.uk page 4/12



MOT #8	2016-04-04 10:21
MOT test number	918469583322

MOT #7 2015-04-02 12:45

MOT test number 469912395019

Result

Passed

MOT #6 2015-04-02 10:31

MOT test number 207182095035

Result X Failed

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #5 2014-04-04 11:44

MOT test number 776364794070

Result \rightarrow Passed

MOT #4 2013-04-08 15:51

MOT test number 128588093477

Result ✓ Passed

MOT #3 2011-11-28 12:26

MOT test number 418462331338

Result
✓ Passed

Advice Nearside Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #2 2010-12-09 09:43

MOT test number 860123040374

CarCheck.co.uk page 5/12



MOT #1 2009-09-19 12:21

MOT test number 354962869226

Result ✓ Passed

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



\sim		100	
Owi	ner	nıs	torv

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NIE NIE
Plate since	
Current registration	OK STEE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-29
Last registration	2022-08-02
Complete history	See info



Registration #1	2006-09-29	25 mi
Registration #2	2009-09-19	70.043 mi
Registration #3	2010-12-09	84.143 mi
Registration #4	2011-11-28	90.784 mi
Registration #5	2013-04-08	99.928 mi
Registration #6	2014-04-04	106.001 mi
Registration #7	2015-04-02	113.895 mi
Registration #8	2015-04-02	113.895 mi
Registration #9	2016-04-04	121.569 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		77.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1402 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1