



General information

Make	FORD
Model	FIESTA ZETEC
Colour	Red
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	E





## MOT history

MOT expiry date	2025-01-25
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	27
Total items failed	9

MOT #17 2024-01-05 15:51

MOT test number 133988960384

Result ✓ Passed

Next expiry date 2025-01-25

**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**Minor** Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))

MOT #16 2024-01-05 09:10

MOT test number 571411592463

Result ✗ Failed

**Minor** Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Exhaust heat shield insecure

**Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MOT #15 2023-01-19 11:19

MOT test number 922768409337

Result ✓ Passed

**MOT #14** 2022-01-20 13:13**MOT test number** 731984274919**Result** ✓ Passed**MOT #13** 2021-01-19 08:33**MOT test number** 874318816060**Result** ✓ Passed**Advice** Nearside Rear tyre cracking on outer wall but showing no cords**MOT #12** 2021-01-15 11:40**MOT test number** 728849135872**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Front Brake pad(s) wearing thin Inner pads. (1.1.13 (a) (ii))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracked/perished. (5.2.3 (d) (iii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Some wear and corrosion to inner surface. (1.1.14 (a) (ii))**MOT #11** 2020-01-20 12:04**MOT test number** 634892480365**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s corroded (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin n/s & o/s (1.1.13 (a) (ii))

**MOT #10**

2020-01-17 09:49

**MOT test number**

947748978968

**Result****✗ Failed****Advice**

Front Inner Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s corroded (1.1.14 (a) (ii))

**Fail**

Offside Front Inner Tyre has ply or cords exposed shoulder (5.2.3 (d) (ii))

**Advice**

Front Brake pad(s) wearing thin n/s & o/s (1.1.13 (a) (ii))

**Advice**

Nearside Front Tyre slightly damaged/cracking or perishing scrubbed off inner shoulder (5.2.3 (d) (ii))

**Fail**

Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #9**

2019-01-16 14:10

**MOT test number**

202196762876

**Result****✓ Passed****Advice**

Rear exhaust heat cover one side insecure

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8**

2018-01-24 08:50

**MOT test number**

132907235631

**Result****✓ Passed****Advice**

Brake disc worn, pitted or scored, but not seriously weakened front discs corroded inner face (3.5.1i)

**Advice**

Lower coil spring corroded n/s/r and o/s/r (2.4.C.1b)

**MOT #7** 2018-01-16 09:41**MOT test number** 760252535014**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened front discs corroded inner face (3.5.1i)**Fail** Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b)**Advice** Lower coil spring corroded n/s/r and o/s/r (2.4.C.1b)**Fail** Windscreen wiper does not clear the windscreen effectively n/s/f and o/s/f (8.2.2)**MOT #6** 2017-01-13 10:09**MOT test number** 867047226848**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #5** 2016-01-12 16:27**MOT test number** 919062554184**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #4** 2015-01-26 15:59**MOT test number** 189236925087**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2014-05-07 17:24**MOT test number** 986697924141**Result** ✓ Passed



MOT #2	2013-05-20 14:29
MOT test number	679960743117
Result	✓ Passed

MOT #1	2013-05-20 12:46
MOT test number	529530843199
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
25 January 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	25 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2010-05-28	11 mi
Registration #2	2013-05-20	20.001 mi
Registration #3	2013-05-20	20.001 mi
Registration #4	2014-05-07	25.095 mi
Registration #5	2015-01-26	29.779 mi
Registration #6	2016-01-12	34.476 mi
Registration #7	2017-01-13	39.348 mi
Registration #8	2018-01-16	43.972 mi
Registration #9	2018-01-24	44.047 mi
Registration #10	2019-05-20	50.277 mi
Registration #11	2019-05-20	50.277 mi
Registration #12	2019-05-20	50.277 mi
Registration #13	2019-05-20	50.277 mi
Registration #14	2019-05-20	50.277 mi
Registration #15	2019-05-20	50.277 mi
Registration #16	2019-05-20	50.277 mi
Registration #17	2019-05-20	50.277 mi
Registration #18	2019-05-20	50.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	9E46444
---------------	---------