




report date: 2024-03-29

General information

Make	VOLVO
Model	S40 SE S40
Colour	Silver
Year of manufacture	2005
Top speed	134 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	224 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.4 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.0 mpg
CO2 emission	217 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2023-10-06
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	33
Total items failed	3

MOT #19	2022-10-07 15:12
MOT test number	200175351451
Result	✓ Passed
Next expiry date	2023-10-06

MOT #18	2022-10-06 11:52
MOT test number	674128327873
Result	✗ Failed
MAJOR Offside Front Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))	

MOT #17	2021-08-27 11:50
MOT test number	188524611596
Result	✓ Passed
Advice Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #16	2020-09-16 15:04
MOT test number	217811141341
Result	✓ Passed

**MOT #15** 2020-09-04 13:14**MOT test number** 611853194921**Result** ✗ Failed**MAJOR** Nearside Front Outline marker lamp not working (4.2.1 (a) (ii))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #14** 2019-09-07 11:52**MOT test number** 954424957339**Result** ✓ Passed**MOT #13** 2018-09-07 15:40**MOT test number** 151583839692**Result** ✓ Passed**Advice** Nearside Rear Suspension component pin or bush slightly worn shock top bump stop (5.3.4 (a) (i))**Advice** Nearside Front brake back plate corroded.**Advice** Both rear tyre worn on inner edges but tread still on 4 mm**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12**

2018-09-06 16:33

MOT test number

615000382645

Result**✗ Failed****DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Both rear tyre worn on inner edges but tread still on 4 mm**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Nearside Rear Play in steering rack inner joint(s)**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Suspension component pin or bush slightly worn shock top bump stop (5.3.4 (a) (i))**Advice** Nearside Front brake back plate corroded.**MOT #11**

2017-09-12 08:41

MOT test number

466646189019

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit tyre worn on inner edge but tread on 2.5 mm (4.1.E.1)

**MOT #10** 2017-08-25 14:38**MOT test number** 320402975987**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Oil leak**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2016-09-09 14:26**MOT test number** 609983906266**Result** ✓ Passed**MOT #8** 2015-09-01 12:40**MOT test number** 671389185794**Result** ✓ Passed**MOT #7** 2014-08-07 17:11**MOT test number** 147179214253**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** The o/s/r bump stop is worn.

**MOT #6** 2013-08-01 13:00**MOT test number** 868453713252**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-08-17 16:59**MOT test number** 877090532272**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-08-11 11:44**MOT test number** 549723721233**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-08-27 11:23**MOT test number** 933719030267**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-06-26 14:53**MOT test number** 582937579128**Result** ✓ Passed



MOT #1	2008-06-27 17:07
MOT test number	593179178176
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
6 October 2023

Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-01
Last registration	2022-10-07
Complete history	See info



Registration #1	2005-07-01	13 mi
Registration #2	2008-06-27	59.079 mi
Registration #3	2009-06-26	82.833 mi
Registration #4	2010-08-27	106.191 mi
Registration #5	2011-08-11	122.466 mi
Registration #6	2012-08-17	137.450 mi
Registration #7	2013-08-01	148.959 mi
Registration #8	2014-08-07	161.280 mi
Registration #9	2015-09-01	169.362 mi
Registration #10	2016-09-09	177.110 mi
Registration #11	2017-08-25	182.780 mi
Registration #12	2018-08-25	182.780 mi
Registration #13	2019-08-25	182.780 mi
Registration #14	2020-08-25	182.780 mi
Registration #15	2021-08-25	182.780 mi
Registration #16	2022-08-25	182.780 mi
Registration #17	2023-08-25	182.780 mi
Registration #18	2024-08-25	182.780 mi
Registration #19	2025-08-25	182.780 mi
Registration #20	2026-08-25	182.780 mi
Registration #21	2027-08-25	182.780 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1481 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	3647519