



RF58BHK


report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE S
Colour	Grey
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-09
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-28
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	41
Total items failed	14

MOT #18	2024-04-18 13:50
MOT test number	360347590432
Result	✓ Passed
Next expiry date	2025-04-28

MOT #17	2023-03-30 13:00
MOT test number	857522689262
Result	✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Suspension component corroded but not seriously weakened shocks and lower arms (5.3.3 (b) (i))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2022-04-29 13:12

MOT test number

945902434233

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #15

2022-04-28 13:18

MOT test number

453036580431

Result

✗ Failed

- Fail** Nearside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Brake fluid contaminated (1.8 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

2021-04-13 15:37

MOT test number

113646500756

Result

✓ Passed

**MOT #13**

2021-04-09 10:40

MOT test number

178575159277

Result**✗ Failed**

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #12

2020-03-26 14:41

MOT test number

118661164992

Result**✓ Passed**

- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2020-03-26 13:51

MOT test number

405140143419

Result**✗ Failed**

- Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2019-04-18 14:25

MOT test number

379754442843

Result

✓ Passed

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Brake fluid slightly contaminated**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Items removed from driver's view prior to test**MOT #9**

2018-03-24 14:48

MOT test number

875252234677

Result

✓ Passed

Advice Front Brake pad(s) modified but not seriously weakened (3.5.1n)**Advice** Nearside Rear badly worn on inner edge**Advice** Rear Brake pad(s) wearing thin very low (3.5.1g)**Advice** Offside Rear tyre badly worn on inner edge**MOT #8**

2018-03-24 13:06

MOT test number

153067996084

Result

✗ Failed

Advice Rear Brake pad(s) wearing thin very low (3.5.1g)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Nearside Rear badly worn on inner edge**Advice** Front Brake pad(s) modified but not seriously weakened (3.5.1n)**Advice** Offside Rear tyre badly worn on inner edge

**MOT #7** 2017-03-21 17:31**MOT test number** 341902250264**Result** ✓ Passed

- Advice** Nearside Front tyre on 3mm
- Advice** Nearside Rear tyre worn on inner edge
- Advice** Offside Front tyre worn on inner edge close to limits

MOT #6 2017-03-21 12:45**MOT test number** 277233096937**Result** ✗ Failed

- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front tyre on 3mm
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Rear tyre worn on inner edge
- Fail** Nearside Headlamp aim too high (1.8)
- Advice** Offside Front tyre worn on inner edge close to limits

MOT #5 2016-04-06 10:35**MOT test number** 158265143362**Result** ✓ Passed**MOT #4** 2015-04-02 15:00**MOT test number** 678992595084**Result** ✓ Passed

- Notice** Brake pedal feels slightly spongy, but not enough to be considered dangerous



MOT #3	2014-04-04 11:09
MOT test number	996124994007
Result	✓ Passed
MOT #2	2013-04-03 12:45
MOT test number	127103493037
Result	✓ Passed
MOT #1	2011-12-01 12:07
MOT test number	948405231398
Result	✓ Passed
<div><div>Notice</div>Oil leak</div> <div><div>Notice</div>Front brake discs slightly worn</div>	



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
28 April 2025

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	28 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-12-12
Last registration	2024-04-18
Complete history	See info



Registration #1	2008-12-12	18 mi
Registration #2	2011-12-01	27.172 mi
Registration #3	2013-04-03	38.953 mi
Registration #4	2014-04-04	45.872 mi
Registration #5	2015-04-02	50.795 mi
Registration #6	2016-04-06	56.781 mi
Registration #7	2017-03-21	60.978 mi
Registration #8	2017-03-21	60.978 mi
Registration #9	2018-03-24	68.770 mi
Registration #10	2018-03-24	68.771 mi
Registration #11	2019-03-29	75.277 mi
Registration #12	2019-03-29	75.277 mi
Registration #13	2019-03-29	75.277 mi
Registration #14	2019-03-29	75.277 mi
Registration #15	2019-03-29	75.277 mi
Registration #16	2019-03-29	75.277 mi
Registration #17	2019-03-29	75.277 mi
Registration #18	2019-03-29	75.277 mi
Registration #19	2019-03-29	75.277 mi
Registration #20	2019-03-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0804140438546G