





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO DYNAMIC DUALOGIC
Colour	White
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	5.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-06

Pictures 6

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-10-28
Pictures	16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-10
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	23
Total items failed	5

MOT #15		2023-11-06 13:11
MOT test	number	711546539058
Result		✓ Passed
Next expi	ry date	2024-11-10
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Exhaust has a minor leak of exhaust gases middle section to back box (6.1.2 (a))	

MOT #14		2023-11-06 11:31
MOT test	number	828571437089
Result		× Failed
Fail 0	ffside Rear Seat belt buckle not functioning as intended (7.1.2 (d))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Exhaust has a minor leak of exhaust gases middle section to back box (6.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #12
 2021-10-25 13:01

 MOT test number
 407252453763

 Result
 ✓ Passed

MOT #11 2020-11-06 15:47
MOT test number 935707680728

Result \(\sqrt{Passed} \)

Minor Nearside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #10
 2019-11-11 16:48

 MOT test number
 230239522905

 Result
 Passed

MOT test number

164377753559

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Minor Offside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Items on dash

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8 2018-09-17 09:24 382658460002 **MOT** test number Result × Failed Fail Nearside Front Headlamp aim too low and too far to the left. (4.1.2 (a)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e)) **Minor** Offside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i)) **Advice** Items on dash Offside Front Direction indicator incorrect colour (4.4.3 (a)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

 MOT #7
 2017-10-06 10:03

 MOT test number
 174784080463

 Result
 ✓ Passed

MOT #6 2017-10-06 08:40

MOT test number 515694591731

Result ★ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #5

MOT test number

Result

MOT #4

MOT test number

2016-10-11 15:27

148278972343

✓ Passed

MOT #4

2016-08-12 07:36

MOT test number

719350207125

Result
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2015-08-13 08:58 **MOT test number** 698886488942 Result ✓ Passed MOT #2 2014-08-13 15:37 **MOT** test number 888115124259 Result ✓ Passed **Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f) Notice Nail in offside rear tyre

MOT test number

Result

Notice Nail in offside rear tyre

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here .	
HARMAN CO.	

HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NE NE
Plate since	
	Moro info
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-30
Last registration	2023-11-06
Complete history	See info



Registration #1	2010-10-30	21 mi
Registration #2	2013-10-02	20.982 mi
Registration #3	2014-08-13	23.946 mi
Registration #4	2015-08-13	30.528 mi
Registration #5	2016-08-12	37.099 mi
Registration #6	2016-10-11	38.049 mi
Registration #7	2017-10-06	55.182 mi
Registration #8	2017-10-06	55.182 mi
Registration #9	2018-09-17	72.945 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 13/13

Number of axles 2

Engine number 7067463