



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 4

Date 2021-09-22

Pictures 14

Listing price [View report](#)



source: autotrader.co.uk

Entry 3

Date 2021-09-07

Pictures 15

Listing price [View report](#)




source: autotrader.co.uk

Entry 2

Date 2021-07-25

Pictures 19

Listing price [View report](#)



source: autotrader.co.uk

Entry 1



Date 2021-06-04

Pictures

16

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	3

MOT #16 2023-09-05 13:48

MOT test number 474936068302

Result ✓ Passed

Next expiry date 2024-09-04

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15 2023-08-26 13:25

MOT test number 594576593256

Result ✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Headlamp lens slightly defective n/s and o/s/f (4.1.1 (b) (i))
- MAJOR** Coil spring fractured or broken n/s and o/s/f (5.3.1 (b) (i))
- Advice** Brake disc worn, but not excessively n/s and o/s/f (1.1.14 (a) (i))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2022-08-19 13:38**MOT test number** 754502223497**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-08-05 14:37**MOT test number** 569495776992**Result** ✓ Passed**MOT #12** 2020-08-25 13:40**MOT test number** 862568707379**Result** ✓ Passed**MOT #11** 2019-08-21 10:41**MOT test number** 285930691009**Result** ✓ Passed**MOT #10** 2018-08-03 13:23**MOT test number** 197224568039**Result** ✓ Passed**MOT #9** 2018-08-03 11:19**MOT test number** 354962869110**Result** ✗ Failed**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #8** 2017-08-08 08:24**MOT test number** 883431984941**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-08-26 09:47**MOT test number** 271463741593**Result** ✓ Passed**Advice** Park brake has little reserve travel**Advice** Rear wiper split**MOT #6** 2015-08-21 12:18**MOT test number** 780363725517**Result** ✓ Passed**MOT #5** 2015-08-21 11:04**MOT test number** 507212898763**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-08-19 11:35**MOT test number** 767001934221**Result** ✓ Passed**MOT #3** 2013-08-24 11:30**MOT test number** 716436733280**Result** ✓ Passed



MOT #2	2013-08-23 16:39
MOT test number	248805833236
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.B.5b)

MOT #1	2012-08-17 10:40
MOT test number	588540632227
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	WV59CFZ
Plate since	2019-03-29
Current registration	WV59CFZ
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-01
Last registration	2023-09-05
Complete history	See info



Registration #1	2009-09-01	8 mi
Registration #2	2012-08-17	19.067 mi
Registration #3	2013-08-23	21.586 mi
Registration #4	2013-08-24	21.586 mi
Registration #5	2014-08-19	29.379 mi
Registration #6	2015-08-21	36.532 mi
Registration #7	2015-08-21	36.532 mi
Registration #8	2016-08-26	43.776 mi
Registration #9	2017-08-08	51.794 mi
Registration #10	2018-08-03	58.266 mi
Registration #11	2018-08-03	58.266 mi
Registration #12	2019-08-03	65.277 mi
Registration #13	2019-08-03	65.277 mi
Registration #14	2019-08-03	65.277 mi
Registration #15	2019-08-03	65.277 mi
Registration #16	2019-08-03	65.277 mi
Registration #17	2019-08-03	65.277 mi
Registration #18	2019-08-03	65.277 mi
Registration #19	2019-08-03	65.277 mi
Registration #20	2019-08-03	65.277 mi
Registration #21	2019-08-03	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1565 mm
Length	4100 mm
Wheel base	2500 mm
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1386045