





report date: 2024-03-28

#### General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Blue
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

#### Entry 1

Date	2021-10-03
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



APO7YTO report date: 2024-03-28

MOT history

MOT expiry date	2025-01-01
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #17	2024-01-02 09:55
MOT test number	560522889232
Result	<b>✓</b> Passed
Next expiry date	2025-01-01
Advice Rear Brake pipe corroded, covered in grease or other material both sides (1.	1.11 (c))

MOT #16	2022-12-22 09:18
MOT test number	804960873681
Result	✓ Passed

Result	✓ Passed
MOT #15	2022-10-31 09:15
MOT test number	974037019916
Result	<b>×</b> Failed
<b>DANGEROUS</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>DANGEROUS</b> Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Nearside Rear Service brake excessively fluctuating (1.2.1 (e))	
MAJOR Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))	
<b>DANGEROUS</b> Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Rear Brakes imbalanced across an axle (1.2.1 (b) (i))	

CarCheck.co.uk page 3/12

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))



Advice

**AP07YTO** 

report date: 2024-03-28

MOT #14	2021-11-08 09:04
MOT test nur	938247408919
Result	✓ Passed
MOT #13	2020-10-12 07:57
MOT test nur	<b>nber</b> 546647635897
Result	✓ Passed
Advice Of	ffside Front Tyre worn close to legal limit/worn on edge NO tread showing on inner edge (5.2.3

Offside Play in steering rack inner joint(s)

MOT #12	2019-10-09 07:21
MOT test number	837521556376
Result	✓ Passed
MOT #11	2018-09-27 08:21
MOT test number	844863697766
MOT test number Result	844863697766 • Passed

MOT #10	2017-09-27 08:09
MOT test number	229285067409
Result	✓ Passed
MOT #9	2016-10-07 08:16
MOT test number	505753365526
Result	✓ Passed
MOT #8	2015-09-23 14:36
MOT test number	280973835229
Result	✓ Passed
MOT test number	280973835229

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7 2014-10-22 12:34

**MOT test number** 838665794299

MOT #6 2014-10-22 12:34

**MOT test number** 909605294295

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5 2014-04-24 11:15

**MOT test number** 517944814188

**Result** 
✓ Passed

MOT #4 2013-05-07 15:45

**MOT test number** 219127623489

**Result** ✓ Passed

MOT #3 2012-04-26 14:21

**MOT test number** 175267512196

MOT #2 2011-05-10 11:39

**MOT test number** 167280331182

MOT #1 2010-04-27 11:14

**MOT test number** 733087710156

**Result** ✓ Passed

CarCheck.co.uk page 5/12



APO7YTO report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-10
Last registration	2024-01-02
Complete history	See info



Registration #1	2007-05-10	8 mi
Registration #2	2010-04-27	12.129 mi
Registration #3	2011-05-10	15.099 mi
Registration #4	2012-04-26	18.724 mi
Registration #5	2013-05-07	21.870 mi
Registration #6	2014-04-24	24.901 mi
Registration #7	2014-10-22	26.957 mi
Registration #8	2015-09-23	32.459 mi
Registration #9	2016-10-07	37.828 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		10.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

# The HYUNDAI factory car options list is only available in the premium report.

 S0225
 Air conditioning

 S0295
 S0482

 S0501
 S0566

 S0567
 S0569

View the complete HYUNDAI factory list for this vehicle  $\underline{\text{here}}.$ 

More info >

#### Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

**Engine number** 

G4EE7705908